

Figure 2-7. Severe corrosion and encrustation was observed (a) at the top of the manifold and (b) - (d) on several module components and 304SS specimens after running the autoclave at 125°C.