LICENSEE EVENT REPORT

TEIR-77-2-8

CONTROL BLOCK: (1–6)

(PLEASE PRINT ALL REQUIRED INFORMATION)

	LICENSEE NAME	LICENSE NUMBER	LICENSE TYPE	EVENT TYPE
01	NYIPS2	00-0000-00	4111	99

	CATEGORY	REPORT TYPE	REPORT SOURCE	DOCKET NUMBER	EVENT DATE	REPORT DATE
01 CON'T		O	L	050-0247	090777	092977

EVENT DESCRIPTION

02 During normal operation, a leak was discovered from the shaft packing
03 gland of No. 26 Service Water Pump. Although the pump was still oper-
04 able, the pump was removed from service for repacking, to prevent further
05 deterioration. An essential header was reestablished and the pump was
06 returned to service within the time period permitted by Technical Speci-

	SYSTEM CODE	CAUSE CODE	COMPONENT CODE	PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER	VIOLATION
07	WA	E	PUMPXX	N	L095	N

CAUSE DESCRIPTION

08 The shaft packing gland of a Layne-Bowler, vertiline close coupled pump
09 was leaking. The gland was repacked with John Crane Packing, Type 5811.
10

	FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
11	E	100	NA	B	Routine Surveillance

	FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
12	Z	Z	NA	NA

PERSONNEL EXPOSURES

	NUMBER	TYPE	DESCRIPTION
13	000	Z	NA

PERSONNEL INJURIES

	NUMBER	DESCRIPTION
14	000	NA

PROBABLE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

	TYPE	DESCRIPTION
16	Z	NA

PUBLICITY

17 NA

ADDITIONAL FACTORS

18 (Event Desc. Cont.) - fications. [TEIR-77-2-8]

19

8111040004 770929
PDR ADOCK 05000247
S PDR

NAME John M. Makepeace PHONE 914-739-8823