LICENSEE EVENT REPORT R.O.-77-2-8(B)

CONTROL BLOCK: [ ] (1–6)

(PLEASE PRINT ALL REQUIRED INFORMATION)

	LICENSEE NAME	LICENSE NUMBER	LICENSE TYPE	EVENT TYPE
01	NYIPS2	00-00000-00	4111	03
(7–8)	(9–14)	(15–25)	(26–30)	(31–32)

	CATEGORY	REPORT TYPE	REPORT SOURCE	DOCKET NUMBER	EVENT DATE	REPORT DATE
01 CONT		L	L	050-0247	032977	042777
(7–8)	(57–58)	(59)	(60)	(61–68)	(69–74)	(75–80)

EVENT DESCRIPTION

02 During normal operation, a visual inspection revealed a leak at a
03 socket weld on the relief valve connection for No. 23 Charging Pump.
04 The pump was shutdown and isolated to effect the necessary repair.
05 Similar events occurred on July 29, 1975, February 1, 1977, March 11,
06 1977 and March 15, 1977. [R.O.-77-2-8(B)]

	SYSTEM CODE	CAUSE CODE	COMPONENT CODE	PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER	VIOLATION
07	PC	E	PIPEXX	N	Z999	N
(7–8)	(9–10)	(11)	(12–17)	(43)	(44–47)	(48)

CAUSE DESCRIPTION

08 The weld leak was attributed to excessive vibration in the charging
09 system. Efforts continue on ways to reduce the probability of a recur-
10 rence.

	FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
11	E	100	NA	B	Routine Inspection
(7–8)	(9)	(10–12)	(13–44)	(45)	(46–80)

	FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
12	Z	Z	NA	NA
(7–8)	(9)	(10)	(11–44)	(45–80)

PERSONNEL EXPOSURES

	NUMBER	TYPE	DESCRIPTION
13	000	Z	NA
(7–8)	(9–11)	(12)	(13–80)

PERSONNEL INJURIES

	NUMBER	DESCRIPTION
14	000	NA
(7–8)	(9–11)	(12–80)

PROBABLE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

	TYPE	DESCRIPTION
16	Z	NA
(7–8)	(9)	(10–80)

PUBLICITY

17 NA

ADDITIONAL FACTORS

18 NA

19

8111040472 770427
PDR ADOCK 05000247
S PDR

NAME: John M. Makepeace PHONE: 914-739-8823