LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] (1–6)

(PLEASE PRINT ALL REQUIRED INFORMATION)

01	LICENSEE NAME	LICENSE NUMBER	LICENSE TYPE	EVENT TYPE
	NYIPS3 (7–14)	00-00000-00 (15–25)	4111 (26–30)	03 (31–32)

01 CON'T	CATEGORY	REPORT TYPE	REPORT SOURCE	DOCKET NUMBER	EVENT DATE	REPORT DATE
	[ ] (57–58)	L (59)	L (60)	05000286 (61–68)	060876 (69–74)	070876 (75–80)

EVENT DESCRIPTION

02 During startup testing, No. 31 Battery Charger AC Breaker tripped, ren-
03 dering the battery charger inoperative. A controlled shutdown was ini-
04 tiated. It was discovered that the pressure sensor for the charger fan
05 had failed. The sensor was jumpered out, the battery charger was re-
06 turned to service, and the shutdown was halted. [R.O.-76-3-18(B)].

07	SYSTEM CODE	CAUSE CODE	COMPONENT CODE	PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER	VIOLATION
	EC (9–10)	E (11)	INSTRU (12–17)	N (43)	X999 (44–47)	N (48)

CAUSE DESCRIPTION

08 A Fairchild, Model PSF-100A, pressure sensor failed, tripping the AC
09 Breaker for No. 31 Battery Charger.
10

11	FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
	B (9)	073 (10–12)	NA (13–44)	A (45)	Control Room Panel Alarm (46–80)

12	FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
	Z (9)	Z (10)	NA (11–44)	NA (45–80)

PERSONNEL EXPOSURES

13	NUMBER	TYPE	DESCRIPTION
	000 (9–11)	Z (12)	NA (13–80)

PERSONNEL INJURIES

14	NUMBER	DESCRIPTION
	000 (9–11)	NA (12–80)

PROBABLE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

16	TYPE	DESCRIPTION
	Z (9)	NA (10–80)

PUBLICITY

17 NA

ADDITIONAL FACTORS

18 NA

8111070536 760708
PDR ADOCK 05000286
S PDR

19

NAME: Austin J. Decker II PHONE: 914-739-8823