NRC FORM 366 (7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 LICENSEE CODE (2)	N Y I P S 3
LICENSE NUMBER (3)	0 0 - 0 0 0 0 0 - 0 0
LICENSE TYPE (4)	4 1 1 1 1
CAT (5)	
CON'T 01 REPORT SOURCE (6)	L
DOCKET NUMBER (7)	0 5 0 0 0 2 8 6
EVENT DATE (8)	0 7 0 3 7 8
REPORT DATE (9)	0 8 0 2 7 8

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While shutdown for refueling, performance of
03 Periodic Test, 3PT-M36 showed that Steam
04 Generator Sample Valves 1223A, 1224A, 1225A
05 and 1226A would not close on a high
06 radiation signal.
07
08

09	
SYSTEM CODE (11)	P B
CAUSE CODE (12)	E
CAUSE SUBCODE (13)	B
COMPONENT CODE (14)	I N S T R U
COMP. SUBCODE (15)	S
VALVE SUBCODE (16)	Z

(17) LER/RO REPORT NUMBER

EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
7 8	—	0 1 4	/	0 3	L	—	0

ACTION TAKEN (18)	FUTURE ACTION (19)	EFFECT ON PLANT (20)	SHUTDOWN METHOD (21)	HOURS (22)	ATTACHMENT SUBMITTED (23)	NPRD-4 FORM SUB. (24)	PRIME COMP. SUPPLIER (25)	COMPONENT MANUFACTURER (26)
Z	B	Z	Z	0 0 0 0	N	Y	N	X 9 9 9

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Failure of Snap Lock, Model D2400X, limit
11 switches on the sample valves is suspected
12 to have prevented the valves from closing.
13 Investigation of the problem is continuing.
14

15	
FACILITY STATUS (28)	H
% POWER (29)	0 0 0
OTHER STATUS (30)	NA
METHOD OF DISCOVERY (31)	B
DISCOVERY DESCRIPTION (32)	Surveillance Test

16	
ACTIVITY RELEASED (33)	Z
CONTENT OF RELEASE (34)	Z
AMOUNT OF ACTIVITY (35)	NA
LOCATION OF RELEASE (36)	NA

17 PERSONNEL EXPOSURES	
NUMBER (37)	0 0 0
TYPE (38)	Z
DESCRIPTION (39)	NA

18 PERSONNEL INJURIES	
NUMBER (40)	0 0 0
DESCRIPTION (41)	NA

19 LOSS OF OR DAMAGE TO FACILITY (43)	
TYPE (42)	Z
DESCRIPTION	NA

20 PUBLICITY	
ISSUED (44)	N
DESCRIPTION (45)	NA

8111090727 780801
PDR ADOCK 05000286
S PDR

NRC USE ONLY

NAME OF PREPARER Neil A. Passman

PHONE: 914-739-8200 X250

GPO 917-926