**Figure 2.5-132 {Shale Outcrop at the Site with Steeply Dipping Beds (85 Degrees to the ENE)}**


© 2008 UniStar Nuclear Services, LLC. All rights reserved.
COPYRIGHT PROTECTED

**Figure 2.5-133 {Fractured Shale in Borrow Area Along Highway 11, Showing No Offset of the Glacial Till Contact}**


© 2008 UniStar Nuclear Services, LLC. All rights reserved.
COPYRIGHT PROTECTED

Figure 2.5-134 {Shale in Borrow Area Dipping 15 Degrees, and Overlain by Glacial Till}


© 2008 UniStar Nuclear Services, LLC. All rights reserved.
COPYRIGHT PROTECTED