NRC FORM 591M PART 1
(10-2003)
10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:	2. NRC/REGIONAL OFFICE
Greenwich Hospital Association 5 Perryridge Road Greenwich, Connecticut 06830 REPORT Nos 2010-001	**U.S. Nuclear Regulatory Commission** **Region I, 475 Allendale Road** **King of Prussia, Pennsylvania 19406-1415**

3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE(S) OF INSPECTION
030-01276	06-09522-01	5/27/10, additional info received 6/4/10, 7/7/10, and 7/27/10

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

☐ 1. Based on the inspection findings, no violations were identified.

☐ 2. Previous violation(s) closed.

☒ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

☒ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

10 CFR 35.75(a) requires in part, that a licensee may authorize the release from its control of any individual who has been administered unsealed byproduct material or implants containing byproduct material if the total effective dose equivalent to any other individual from exposure to the released individual is not likely to exceed 5 mSv (0.5 rem).

Contrary to the above, as of May 27, 2010, the licensee authorized the release from its control individuals who had been administered I-131 doses greater than 33 millicuries prior to confirming that the total effective dose equivalent to any other individual from exposure to the released individual was not likely to exceed 5 mSv (0.5 rem). Specifically, the licensee performed dose calculations that confirmed patient releasibility after the patient was released.

The licensee's corrective actions included revising their procedures to require the completion of patient release calculation worksheets, prior to release, and retraining staff on the revised procedures.

☐ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Ralph Scambato	Ralph Scambato	8/2/2010
NRC INSPECTOR	Janice Nguyen	Janice Nguyen	7-29-10

SUNSI Review Completed By: /RA/ Janice Nguyen ☒ Public ☒ Non-Sensitive