**Lew, David**

**From:** Catts, Michelle -R1
**Sent:** Sunday, November 07, 2010 11:07 PM
**To:** Gray, Mel; Bickett, Brice; Lew, David; Cataldo, Paul; Halter, Mandy; Ayegbusi, Odunayo; Sheehan, Neil; Screnci, Diane; Tifft, Doug; McNamara, Nancy; Roberts, Darrell; Wilson, Peter
**Subject:** Indian Point Unit 2 Trip Update

Outside of Scope

OUT-OF-SCOPE

**NRC Preliminary Assessment**

Preliminarily, the inspectors determined the plant responded as designed with no complications or additional safety issues.

The inspectors walked down the safety related areas of the plant including the 480V room, the auxiliary feedwater pump room, control room, and the area surrounding the 21 main transformer. The inspectors did not identify any safety related equipment issues.

Information in this record was deleted in accordance with the Freedom of Information Act. Exemptions Outside of Scope
FOIA/PA 2011-0045



B/2

A couple items to note:

1. The 480V room dampers close on a transformer deluge activation. This occurred as designed. Room temperature peaked around 100F with the limit being 104F. The licensee has compensatory measures in place including opening doors (with security present) and running fans.
2. A water/oil mixture was unexpectedly found in the turbine building on the other side of the wall from the transformer, but did not affect any equipment.

Outside of Scope

OUT-OF-SCOPE

If you have any additional questions, please let me know.

Thanks!

Michelle Catts
Senior Resident Inspector, Indian Point Unit 2
U.S. NRC