SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED;	2. NRC/REGIONAL OFFICE
Department of the Army Watervliet Arsenal, 1 Buffington Street Watervliet, New York 12189-4000 REPORT NUMBER(S) 2013-001	**U.S. Nuclear Regulatory Commission** **Region I, 2100 Renaissance Blvd, Suite 100** **King of Prussia, Pennsylvania 19406-2713**

3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE(S) OF INSPECTION
030-05533	31-07595-01	May 21, 23, and 29, 2013

(Continued)

10 CFR 30.36(d) requires, in part, that licensees provide notification to the NRC in writing within 60 days of any of the following occurrences:

1. The license has expired,
2. The licensee has decided to permanently cease principal activities at the entire site or in any separate building or outdoor area that contains residual radioactivity such that the building or outdoor area is unsuitable for release in accordance with NRC requirements,
3. No principal activities under the license have been conducted for a period of 24 months, or
4. No principal activities have been conducted for a period of 24 months in any separate building or outdoor area that contains residual radioactivity such that the building or outdoor area is unsuitable for release in accordance with NRC requirements.

Contrary to the above, as of May 21, 2013, the licensee permanently ceased principal activities conducted under Byproduct Material License No. 31-07595-01 for a period of 24 months, and the licensee failed to notify the NRC in writing within 60 days of this occurrence.

The Radiation Safety Officer committed that he would send in notification as required by 10 CFR 30.36(d) within 30 days.