NRC FORM 591M PART 1
(07-2012)
10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:	2. NRC/REGIONAL OFFICE
JanX Integrity Group 8550 E. Michigan Avenue Parma, MI 49269 Location inspected: Montezuma, IN REPORT NUMBER(S) 2015-002	Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352

3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE(S) OF INSPECTION
030-11772	21-16560-01	April 2, 2015

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

☑ 1. Based on the inspection findings, no violations were identified.

☐ 2. Previous violation(s) closed.

☐ 3. The violations(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

_____ Non-cited violation(s) were discussed involving the following requirement(s):

☐ 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Ryan Craffey	Ryan Craffey	4/7/15
BRANCH CHIEF	Aaron McCraw		4/8/15

NRC FORM 591M PART 3
(07-2012)
10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:	2. NRC/REGIONAL OFFICE
JanX Integrity Group 8550 E. Michigan Avenue Parma, MI 49269 Location inspected: Montezuma, IN REPORT NUMBER(S) 2015-002	Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352

3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE(S) OF INSPECTION
030-11772	21-16560-01	April 2, 2015

6. INSPECTION PROCEDURES USED	7. INSPECTION FOCUS AREAS
87121, 87137	All

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S)	2. PRIORITY	3. LICENSEE CONTACT	4. TELEPHONE NUMBER
03320	1	William Reeve - RSO	(517) 531-8210

☐ Main Office Inspection Next Inspection Date: No change

☑ Field Office Inspection 6127 West US 36, Montezuma, IN

☐ Temporary Job Site Inspection

PROGRAM SCOPE

This was an unannounced routine inspection of a large non-destructive testing company authorized to use radioactive material for industrial radiography at numerous field stations and at temporary job sites throughout NRC jurisdiction. The licensee maintained a field station at the Big Inch Fabricators facility in Montezuma, Indiana from 8:00 am to 3:30 pm each weekday to perform pipe weld inspections on-site when necessary. The licensee provided equipment and sources from its main office in Parma, Michigan.

PERFORMANCE OBSERVATIONS

The inspector was unable to observe the conduct of actual radiographic operations at the facility, as all work had been completed prior to arrival. However, the on-site crew, as well as two additional crews who were at the site during the inspection, were able to demonstrate and discuss the implementation of licensee procedures for equipment maintenance, restricted area barrier use, hazardous material transportation, emergency response, and refresher training. Through these demonstrations and discussions, the inspector found that the radiographers and assistants were knowledgeable of radiation protection principles and licensee procedures, and that their dosimetry and instrumentation was calibrated and operable.

The inspector conducted independent and confirmatory surveys of the licensee's on-site storage location, as well as the two rigs temporarily parked at the facility; the inspector found no exposures to members of the public in excess of regulatory limits. The inspector also noted that each camera was in good working order and was properly labeled, and reviewed a selection of utilization logs and shipping papers for each camera.

No violations of NRC safety requirements were identified as a result of this inspection.