(7-77)

LICENSEE EVENT REPORT

CONTROL BLOCK: [. | | | | |] (1) (PLEASE PRINT OR [illegible]E ALL REQUIRED INFORMATION)

Line	Field	Entry
01	LICENSEE CODE (9–14)	I L D R S 3 (2)
	LICENSE NUMBER (15–25)	0 0 - 0 0 0 0 0 - 0 0 (3)
	LICENSE TYPE (26–30)	4 1 1 1 1 (4)
	CAT (57–58)	(5)
CON'T 01	REPORT SOURCE (60)	L (6)
	DOCKET NUMBER (61–68)	0 5 0 0 0 2 4 9 (7)
	EVENT DATE (69–74)	0 5 0 3 7 9 (8)
	REPORT DATE (75–80)	0 5 2 4 7 9 (9)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During routine inspection, pinhole leak found on cleanup equalizing line (2-1292-2").

03 Leak was located on 2 inch pipe to coupling socket weld. System operation not de-

04 graded. No previous leaks of this nature have occurred. No adverse effects on public

05 health or safety since minimal leakage contained in reactor building floor drain sys-

06 tem, and line located outside primary containment isolation valves.

07

08

Line	SYSTEM CODE (9–10)	CAUSE CODE (11)	CAUSE SUBCODE (12)	COMPONENT CODE (13–18)	COMP. SUBCODE (19)	VALVE SUBCODE (20)
09	C G (11)	E (12)	C (13)	P I P E X X (14)	A (15)	Z (16)

(17) LER/RO REPORT NUMBER

EVENT YEAR (21–22)	(23)	SEQUENTIAL REPORT NO. (24–26)	(27)	OCCURRENCE CODE (28–29)	REPORT TYPE (30)	(31)	REVISION NO. (32)
7 9	—	0 0 8	/	0 3	L	—	0

ACTION TAKEN (33)	FUTURE ACTION (34)	EFFECT ON PLANT (35)	SHUTDOWN METHOD (36)	HOURS (37–40)	ATTACHMENT SUBMITTED (41)	NPRD-4 FORM SUB. (42)	PRIME COMP. SUPPLIER (43)	COMPONENT MANUFACTURER (44–47)
B (18)	Z (19)	Z (20)	Z (21)	0 0 0 0 (22)	N (23)	N (24)	N (25)	P 2 1 2 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Possible cause is erosion due to flow characteristics and possibly cavitation. The

11 leak was repaired by removing the entire weld and rewelding the 2 inch pipe to the

12 coupling. No further corrective action deemed necessary.

13

14

Line	FACILITY STATUS (9)	% POWER (10–12)	OTHER STATUS (13–44) (30)	METHOD OF DISCOVERY (45)	DISCOVERY DESCRIPTION (46–80) (32)
15	E (28)	0 8 6 (29)	N/A	B (31)	Routine Inspection

Line	ACTIVITY RELEASED (9)	CONTENT OF RELEASE (10)	AMOUNT OF ACTIVITY (11–44) (35)	LOCATION OF RELEASE (45–80) (36)
16	Z (33)	Z (34)	N/A	N/A

PERSONNEL EXPOSURES

Line	NUMBER (9–11)	TYPE (12)	DESCRIPTION (13–80) (39)
17	0 0 0 (37)	Z (38)	N/A

PERSONNEL INJURIES

Line	NUMBER (9–11)	DESCRIPTION (12–80) (41)
18	0 0 0 (40)	N/A

LOSS OF OR DAMAGE TO FACILITY (43)

Line	TYPE (9)	DESCRIPTION (10–80)
19	Z (42)	N/A

7905300705

PUBLICITY

Line	ISSUED (9)	DESCRIPTION (10–68) (45)	NRC USE ONLY (69–80)
20	N (44)	N/A	

NAME OF PREPARER T. Jansen PHONE: X-265

7905300

GPO 917-926