ACCELERATED DOCUMENT DISTRIBUTION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9308090327 DOC.DATE: 93/07/29 NOTARIZED: NO DOCKET #
FACIL:50-244 Robert Emmet Ginna Nuclear Plant, Unit 1, Rochester G 05000244
AUTH.NAME AUTHOR AFFILIATION
MECREDY,R.C. Rochester Gas & Electric Corp.
RECIP.NAME RECIPIENT AFFILIATION
Document Control Branch (Document Control Desk)

SUBJECT: Forwards Rev 1 to LER 92-006 re FW control perturbations due to secondary side transient,causing SG high level FW isolations.Rev provides update on root cause determination & further corrective actions as committed to LER 92-006-00.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1+11
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:License Exp date in accordance with 10CFR2,2.109(9/19/72). 05000244

	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL
	PD1-3 LA	1	1	PD1-3 PD	1	1
	JOHNSON,A	1	1			
INTERNAL:	ACNW	2	2	AEOD/DOA	1	1
	AEOD/DSP/TPAB	1	1	AEOD/ROAB/DSP	2	2
	NRR/DE/EELB	1	1	NRR/DE/EMEB	1	1
	NRR/DORS/OEAB	1	1	NRR/DRCH/HHFB	1	1
	NRR/DRCH/HICB	1	1	NRR/DRCH/HOLB	1	1
	NRR/DRIL/RPEB	1	1	NRR/DRSS/PRPB	2	2
	NRR/DSSA/SPLB	1	1	NRR/DSSA/SRXB	1	1
	REG FILE 02	1	1	RES/DSIR/EIB	1	1
	RGN1 FILE 01	1	1			
EXTERNAL:	EG&G BRYCE,J.H	2	2	L ST LOBBY WARD	1	1
	NRC PDR	1	1	NSIC MURPHY,G.A	1	1
	NSIC POORE,W.	1	1	NUDOCS FULL TXT	1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
TOTAL NUMBER OF COPIES REQUIRED: LTTR 30 ENCL 30

RIDS/ADDS

RIDS/ADDS

ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER N.Y. 14649-0001

ROBERT C. MECREDY
Vice President
Ginna Nuclear Production

TELEPHONE
AREA CODE 716 546-2700

July 29, 1993

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Subject: LER 92-006, (Revision 1) Feedwater Control Perturbations, Due To A Secondary Side Transient, Causes Steam Generator High Level Feedwater Isolations
R.E. Ginna Nuclear Power Plant
Docket No. 50-244

In accordance with 10CFR50.73, Licensee Event Report System, item (a)(2)(iv), which requires a report of, "any event or condition that resulted in manual or automatic actuation of any Engineered Safety Feature (ESF), including the Reactor Protection System (RPS)", the attached Event Report LER 92-006 (Revision 1) is hereby submitted. This revision is being submitted to provide an update on the root cause determination and further corrective action as committed to in LER 92-006 (Revision 0). Shaded text denotes Revision 1 material.

This event has in no way affected the public's health and safety.

Very truly yours,

Robert C. Mecredy

Robert C. Mecredy

xc: U.S. Nuclear Regulatory Commission
Region I
475 Allendale Road
King of Prussia, PA 19406

Ginna USNRC Senior Resident Inspector

050001

IE22
1/1

9308090327 930729
PDR ADOCK 05000244
S PDR