NRC FORM 366 (7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	NYNMP1 (2)	00-00000-00 (3)	41111 (4)	(5)	
	LICENSEE CODE	LICENSE NUMBER	LICENSE TYPE	CAT	

CON'T

01	REPORT SOURCE L (6)	05000220 (7)	042479 (8)	052379 (9)	
		DOCKET NUMBER	EVENT DATE	REPORT DATE	

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During refueling outage, containment vacuum relief valve (68 IV-10)

03 flange failed its leak rate test. This resulted in minimal safety

04 implications since the unit was shutdown for refueling.

05

06

07

08

09

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
SD (11)	E (12)	X (13)	VALVEX (14)	B (15)	C (16)

(17) LER RO REPORT NUMBER

EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
79	—	010	/	03	L	—	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
A (18)	Z (19)	Z (20)	Z (21)	0000	N (23)	N (24)	A (25)	A180 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 O-rings were replaced on flange of containment vacuum relief valve

11 (68 IV-10), which subsequently passed its leak rate test.

12

13

14

FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
15 H (28)	000 (29)	NA	B (31)	Leak Rate Test

ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
16 Z (33)	Z (34)	NA	NA

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION (39)
17 000 (37)	Z (38)	NA

PERSONNEL INJURIES

NUMBER	DESCRIPTION (41)
18 000 (40)	NA

LOSS OF OR DAMAGE TO FACILITY (43)

TYPE	DESCRIPTION
19 Z (42)	NA

PUBLICITY

ISSUED	DESCRIPTION (45)
20 N (44)	NA

NRC USE ONLY

NAME OF PREPARER E. Duda

PHONE: (315)343-2110 Ext 1306

7905300496

GPO 917-926