NRC FORM 366
(7-77)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	NYNMP1 (2) LICENSEE CODE	00-00000-00 (3) LICENSE NUMBER	4 (4) LICENSE TYPE	CAT (5)	
CON'T 01	REPORT SOURCE L (6)	05000220 (7) DOCKET NUMBER	051079 (8) EVENT DATE	053179 (9) REPORT DATE	

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During refueling outage, Containment Spray Heat Exchangers 112 and 121
03 failed a leak rate test. This has minimal safety implications since
04 the unit is off-line for refueling.
05
06
07
08

09	SYSTEM CODE SB (11)	CAUSE CODE E (12)	CAUSE SUBCODE X (13)	COMPONENT CODE HTEXCH (14)	COMP. SUBCODE C (15)	VALVE SUBCODE Z (16)		
(17) LER RO REPORT NUMBER	EVENT YEAR 79	—	SEQUENTIAL REPORT NO. 008	/	OCCURRENCE CODE 03	REPORT TYPE L	—	REVISION NO. 0
ACTION TAKEN B (18)	FUTURE ACTION Z (19)	EFFECT ON PLANT Z (20)	SHUTDOWN METHOD Z (21)	HOURS (22) 0000	ATTACHMENT SUBMITTED N (23)	NPRD-4 FORM SUB. N (24)	PRIME COMP. SUPPLIER L (25)	COMPONENT MANUFACTURER W315 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Containment Spray Heat Exchangers 112 and 121 failed their leak rate
11 test due to tube leaks. These tubes were plugged and each heat exchanger
12 passed a subsequent leak rate test.
13
14

15	FACILITY STATUS H (28)	% POWER 000 (29)	OTHER STATUS (30) NA	METHOD OF DISCOVERY B (31)	DISCOVERY DESCRIPTION (32) Leak Rate Test
16	ACTIVITY RELEASED Z (33)	CONTENT OF RELEASE Z (34)	AMOUNT OF ACTIVITY (35) NA	LOCATION OF RELEASE (36) NA	
17	PERSONNEL EXPOSURES NUMBER 000 (37)	TYPE Z (38)	DESCRIPTION (39) NA		
18	PERSONNEL INJURIES NUMBER 000 (40)	DESCRIPTION (41) NA			
19	LOSS OF OR DAMAGE TO FACILITY (43) TYPE Z (42)	DESCRIPTION NA			
20	PUBLICITY ISSUED N (44)	DESCRIPTION (45) NA		NRC USE ONLY	

7906110181

NAME OF PREPARER E. Duda PHONE: 315-343-2110 Ext. 1306

GPO 917-926