PALISADES PLANT

NRC FORM 366 (7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: [| | | | | |] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1	LICENSEE CODE: M I P A L 1 (2)	LICENSE NUMBER: 0 0 - 0 0 0 0 0 - 0 0 (3)	LICENSE TYPE: 4 1 1 1 1 (4)	CAT: (5)			
CON'T 0 1	REPORT SOURCE: L (6)	DOCKET NUMBER: 0 5 0 0 0 2 5 5 (7)	EVENT DATE: 0 5 1 2 8 0 (8)	REPORT DATE: 0 6 1 3 8 0 (9)			

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During routine testing of hydraulic snubbers, the oil level in snubber

0 3 number 9 was found to be less than zero, and the snubber was declared

0 4 inoperable. Event reportable per TS 6.9.2.B.2 and TS 3.20. Event

0 5 classified reportable on 6-9-80.

0 6

0 7

0 8

	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
0 9	H B (11)	E (12)	B (13)	S U P O R T (14)	D (15)	Z (16)

LER/RO REPORT NUMBER (17)	EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
	8 0	—	0 1 5	/	0 3	L	—	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
C (18)	Z (19)	Z (20)	Z (21)	0 0 0 0	N (23)	Y (24)	A (25)	B 2 1 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Upon disassembly of the snubber, the accumulator plunger seal was found to

1 1 be damaged. Cause of seal damage is unknown; normal wear is suspected.

1 2

1 3

1 4

	FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
1 5	G (28)	0 0 0 (29)	NA	B (31)	Surveillance Test

	ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
1 6	Z (33)	Z (34)	NA	NA

PERSONNEL EXPOSURES

	NUMBER	TYPE	DESCRIPTION (39)
1 7	0 0 0 (37)	Z (38)	NA

PERSONNEL INJURIES

	NUMBER	DESCRIPTION (41)
1 8	0 0 0 (40)	NA

LOSS OF OR DAMAGE TO FACILITY (43)

	TYPE	DESCRIPTION
1 9	Z (42)	NA

PUBLICITY

	ISSUED	DESCRIPTION (45)	NRC USE ONLY
2 0	N (44)	NA	

8006190 426