(7-77)

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	N J S G S 1 (2)	0 0 - 0 0 0 0 0 - 0 0 (3)	4 1 1 1 1 (4)	(5)
	LICENSEE CODE	LICENSE NUMBER	LICENSE TYPE	CAT

CON'T

01	REPORT SOURCE L (6)	0 5 0 0 0 2 7 2 (7)	0 8 0 5 8 0 (8)	0 9 0 4 8 0 (9)
		DOCKET NUMBER	EVENT DATE	REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During a routine containment entry, it was determined a roller was broken on the

03 100' elevation outer door. Action Statement 3.6.1.3 was entered at 1550 hours.

04 (77-58, 77-70, 77-73, 78-28, 78-56, 78-75)

05

06

07

08

09

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
S D (11)	E (12)	B (13)	P E N E T R (14)	A (15)	Z (16)

(17) LER/RO REPORT NUMBER

EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
8 0	—	0 4 4	/	0 3	L	—	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
A (18)	Z (19)	Z (20)	Z (21)	0 0 0 0	Y (23)	N (24)	L (25)	C 3 1 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 After repeated use, the roller failed. The roller was replaced and tested

11 satisfactorily. The Action Statement was terminated at 1720 hours.

12

13

14

	FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
15	E (28)	0 8 5 (29)	N/A	B (31)	Routine Surveillance

	ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
16	Z (33)	Z (34)	N/A	N/A

PERSONNEL EXPOSURES

	NUMBER	TYPE	DESCRIPTION (39)
17	0 0 0 (37)	Z (38)	N/A

PERSONNEL INJURIES

	NUMBER	DESCRIPTION (41)
18	0 0 0 (40)	N/A

LOSS OF OR DAMAGE TO FACILITY (43)

	TYPE	DESCRIPTION
19	Z (42)	N/A

PUBLICITY

	ISSUED	DESCRIPTION (45)	NRC USE ONLY
20	N (44)	N/A	

NAME OF PREPARER M. J. Murphy PHONE: 609-935-0998

8009120372

GPO 917-926