NRC FORM 366 (7-77)

LICENSEE EVENT REPORT

CONTROL BLOCK: [| | | | |] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | LICENSEE CODE: N J S G S 1 (2) | LICENSE NUMBER: 0 0 - 0 0 0 0 0 - 0 0 (3) | LICENSE TYPE: 4 1 1 1 1 (4) | CAT: (5)

CON'T 01 | REPORT SOURCE: L (6) | DOCKET NUMBER: 0 5 0 0 0 2 7 2 (7) | EVENT DATE: 0 8 0 6 8 0 (8) | REPORT DATE: 0 9 0 4 8 0 (9)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During routine maintenance on the Air Particulate Detector, it was determined the
03 pump had seized. At 1907 hours, Action Statement 3.4.6.1 was entered (76-2, 76-24,
04 77-53, 79-24).

	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
09	M C (11)	E (12)	B (13)	P U M P X X (14)	A (15)	Z (16)

(17) LER/RO REPORT NUMBER	EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
	8 0	—	0 4 5	/	0 3	L	—	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
C (18)	Z (19)	Z (20)	Z (21)	0 0 0 0	Y (23)	N (24)	L (25)	C 5 2 1 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The pump was replaced and tested satisfactorily. The Action Statement was terminated
11 at 2207 hours.

	FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
15	E (28)	0 8 2 (29)	N/A	B (31)	Routine Maintenance

	ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
16	Z (33)	Z (34)	N/A	N/A

PERSONNEL EXPOSURES

	NUMBER	TYPE	DESCRIPTION (39)
17	0 0 0 (37)	Z (38)	N/A

PERSONNEL INJURIES

	NUMBER	DESCRIPTION (41)
18	0 0 0 (40)	N/A

LOSS OF OR DAMAGE TO FACILITY (43)

	TYPE	DESCRIPTION
19	Z (42)	N/A

PUBLICITY

	ISSUED	DESCRIPTION (45)	NRC USE ONLY
20	N (44)	N/A	

NAME OF PREPARER M. J. Murphy PHONE: 609-935-0998

8009120382

GPO 917-926