REGULATORY DOCKET FILE COPY

USNRC REGION
ATLANTA, GA

79 JUN 25 AM 11:53

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| V | A | S | P | S | 1 | (2) 0 0 - 0 0 0 0 0 - 0 0 (3) 4 1 1 1 0 (4) (5)

LICENSEE CODE / LICENSE NUMBER / LICENSE TYPE / CAT

REPORT SOURCE (6) 0 5 0 0 0 2 8 0 (7) 0 6 2 2 7 9 (8) (9)

DOCKET NUMBER / EVENT DATE / REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

Radiography of Surry Unit 1 Steam Generator Feedwater Nozzles and Reducers revealed crack indications at the counterbore region. Both units are at cold shutdown. Westinghouse and Vepco are evaluating the problem. This report is confirmation of verbal report to NRC on 6/22/79.

SYSTEM CODE (11) CAUSE CODE (12) CAUSE SUBCODE (13) COMPONENT CODE (14) COMP. SUBCODE (15) VALVE SUBCODE (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR / SEQUENTIAL REPORT NO. / OCCURRENCE CODE / REPORT TYPE / REVISION NO.

ACTION TAKEN (18) FUTURE ACTION (19) EFFECT ON PLANT (20) SHUTDOWN METHOD (21) HOURS (22) ATTACHMENT SUBMITTED (23) NPRD-4 FORM SUB. (24) PRIME COMP. SUPPLIER (25) COMPONENT MANUFACTURER (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

FACILITY STATUS (28) % POWER (29) OTHER STATUS (30) METHOD OF DISCOVERY (31) DISCOVERY DESCRIPTION (32)

ACTIVITY CONTENT: RELEASED OF RELEASE (33) (34) AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES: NUMBER (37) TYPE (38) DESCRIPTION (39)

PERSONNEL INJURIES: NUMBER (40) DESCRIPTION (41)

LOSS OF OR DAMAGE TO FACILITY (42): TYPE (43) DESCRIPTION

PUBLICITY: ISSUED (44) DESCRIPTION (45)

NRC USE ONLY

A002
5 0/1

7907200392 S