VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

October 12, 1995

United States Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D. C. 20555

Serial No. 95-512
NL/RPC
Docket No. 50-280
License No. DPR-32

Gentlemen:

VIRGINIA ELECTRIC AND POWER COMPANY
SURRY POWER STATION UNIT 1
STEAM GENERATOR TUBE INSPECTION REPORT

Planned inservice inspection of the Surry Unit 1 "C" steam generator was completed during the 1995 refueling outage. In accordance with Surry Power Station Technical Specifications, Section 4.19.F.a, this letter provides notification of the steam generator tube that was plugged during the outage. One tube (R38-C74) was plugged as a precautionary measure due to a concern with anti-vibration bar wear.

"C" STEAM GENERATOR
TUBE PLUGGED

ROW	COLUMN	
38	74	(precautionary)

If you have any questions concerning these results, please contact us.

Very truly yours,

James P. O'Hanlon

James P. O'Hanlon
Senior Vice President - Nuclear

cc: United States Nuclear Regulatory Commission
Region II
101 Marietta Street, N. W.
Suite 2900
Atlanta, Georgia 30323

Mr. M. W. Branch
NRC Senior Resident Inspector
Surry Power Station

A047
1/0

9510240292 951012
PDR ADOCK 05000280
Q PDR