NRC FORM 195 (2-76)

U.S. NUCLEAR REGULATORY COMMISSION

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

DOCKET NUMBER: 50-315

FILE NUMBER: INCIDENT REPORT

TO:
MR. J. G. KEPPLER

FROM:
INDIANA & MICHIGAN POWER COMPANY
BRIDGMAN, MICHIGAN
R. W. JURGENSEN

DATE OF DOCUMENT: 5/25/76

DATE RECEIVED: 5/28/76

☒ LETTER ☐ ORIGINAL ☒ COPY

☐ NOTORIZED ☒ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED: NONE SIGNED

DESCRIPTION

LTR. TRANS THE FOLLOWING:

(1-P)

ENCLOSURE

LICENSEE EVENT RPT. (RO 50-315/76-22) ON 5/5/76 CONCERNING ISOLATION TIMES EXCEEDING TECH SPEC WHEN RESPONSE TIME TESTING OF VALVES CCR-460 & CCR-462.

ACKNOWLEDGED

(1-P) DO NOT REMOVE

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED SEND DIRECTLY TO KREGER/J. COLLINS

PLANT NAME:
COOK 1

SAFETY — FOR ACTION/INFORMATION — ENVIRO — 5/28/76 — RJL

☒	BRANCH CHIEF:	KNIEL		
	W/3 CYS FOR ACTION			
☒	LIC. ASST:	SERVICE		
	W/1 CYS			
	ACRS 16 CYS HOLDING/SENT TO LA			

INTERNAL DISTRIBUTION

☒	REG FILE				
☒	NRC PDR				
☒	I & E (2)				
☒	MIPC (3)				
☒	SCHROEDER/IPPOLITO				
☒	HOUSTON				
☒	NOVAK/CHECK				
☒	GRIMES/SCHWENCER (1) EA				
☒	CASE				
	~~E. WILLIAMS~~				
☒	HANAUER				
☒	TEDESCO/MACCARY				
☒	EISENHUT				
☒	BAER				
☒	SHAO				
☒	VOLLMER/BUNCH				
☒	KREGER/J. COLLINS				

EXTERNAL DISTRIBUTION

☒	LPDR: ST. JOSEPH,MI.				
☒	TIC				
☒	NSIC				

CONTROL NUMBER: 5366

American Electric Power System
INDIANA & MICHIGAN POWER COMPANY
DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

RECEIVED
MAY 28 1976
U.S. NUCLEAR REGULATORY COMMISSION
Mail Section

May 25, 1976

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of Appendix A Technical Specifications and the United States Nuclear Regulatory Commission Regulatory Guide 1.16, Revision 4, Section 2.b, the following report is submitted:

RO 50-315/76-22

Sincerely,

R.W. Jurgensen
Plant Manager

/bab

cc: R.S. Hunter
J.E. Dolan
G.E. Lien
R. Kilburn
R.J. Vollen BPI
R.C. Callen MPSC
K.R. Baker RO:III
P.W. Steketee, Esq.
R. Walsh, Esq.
G. Charnoff, Esq.
G. Olson
J.M. Hennigan
PNSRC
R.S. Keith
Dir., IE (30 copies)
Dir., MIPC (3 copies)

DOCKETED
USNRC
MAY 28 1976
U.S. NUCLEAR REGULATORY COMMISSION
Mail Section

Regulatory Docket File

5366

LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] (1–6) [PLEASE PRINT ALL REQUIRED INFORMATION]

	LICENSEE NAME	LICENSE NUMBER	LICENSE TYPE	EVENT TYPE
0 1	M I D C C 1	0 0 – 0 0 0 0 0 – 0 0	4 1 1 1 1	0 3
7 8 9	14	15 25	26 30	31 32

	CATEGORY	REPORT TYPE	REPORT SOURCE	DOCKET NUMBER	EVENT DATE	REPORT DATE
0 1 CON'T		L	L	0 5 0 – 0 3 1 5	0 5 0 5 7 6	0 5 2 5 7 6
7 8	57 58	59	60	61 68	69 74	75 80

EVENT DESCRIPTION

0 2 | WHILE IN MODE 5, RESPONSE TIME TESTING OF VALVES CCR-460 AND CCR-462 FOUND ISOLATION
0 3 | TIMES FOR THESE VALVES EXCEEDING THE LIMITS ESTABLISHED IN TECHNICAL SPECIFICATIONS
0 4 | TABLE 3.6-1. (RO-50-315/76-22)
0 5 |
0 6 |

	SYSTEM CODE	CAUSE CODE	COMPONENT CODE	PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER	VIOLATION
0 7	S D	B	Z Z Z Z Z Z	Z	Z Z Z Z	N
7 8 9	10 11	12 17	43	44 47	48	

CAUSE DESCRIPTION

0 8 | THE CAUSE OF THE EXCESSIVE ISOLATION TIMES WAS FOUND TO BE VENT FLOW RESTRICTION DUE TO
0 9 | TUBING BEING 3/8 INCH O.D. RATHER THAN 5/8 INCH O.D. AS REQUIRED ON THE MECHANICAL
1 0 | DRAWINGS. THE CORRECT DIAMETER TUBING WAS INSTALLED.

	FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
1 1	G	0 0 0	NA	B	SURVEILLANCE TESTING
7 8	9	10 12	13 44	45	46 80

	FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
1 2	Z	Z	NA	NA
7 8	9	10	11 44	45 80

PERSONNEL EXPOSURES

	NUMBER	TYPE	DESCRIPTION
1 3	0 0 0	Z	NA
7 8 9	11	12	13 80

PERSONNEL INJURIES

	NUMBER	DESCRIPTION
1 4	0 0 0	NA
7 8 9	11	12 80

PROBABLE CONSEQUENCES

1 5 | NA

LOSS OR DAMAGE TO FACILITY

	TYPE	DESCRIPTION
1 6	Z	NA
7 8 9	10	80

PUBLICITY

1 7 | NA

ADDITIONAL FACTORS

1 9 | NA

1 8 | NA

NAME: G. SWAN PHONE: (616) 465-5901 Ext. 368