U.S. NUCLEAR REGULATORY COMMISSION

POOR ORIGINAL

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 | G A E I H 2 (2) | 0 0 0 0 0 0 0 0 0 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
REPORT SOURCE: L (6) | DOCKET NUMBER: 0 5 0 0 0 3 6 6 (7) | EVENT DATE: 0 9 1 2 7 9 (8) | REPORT DATE: 0 9 1 9 7 9 (9)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

The HPCI flow control loop was found to be inoperative. This deficiency would not allow the system to perform its designed function in manual or auto. There was no affect on the environs. There have been no previous reports of similar occurrences.

SYSTEM CODE: S F (11) | CAUSE CODE: E (12) | CAUSE SUBCODE: E (13) | COMPONENT CODE: I N S T R U (14) | COMP. SUBCODE: C (15) | VALVE SUBCODE: Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 7 9 | SEQUENTIAL REPORT NO. 0 9 6 | OCCURRENCE CODE 0 3 | REPORT TYPE L | REVISION NO. 0

ACTION TAKEN: A (18) | FUTURE ACTION: Z (19) | EFFECT ON PLANT: Z (20) | SHUTDOWN METHOD: Z (21) | HOURS (22): 0 0 0 0 | ATTACHMENT SUBMITTED: N (23) | NPRD-4 FORM SUB.: N (24) | PRIME COMP. SUPPLIER: N (25) | COMPONENT MANUFACTURER: W 2 9 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

Investigations revealed a bad ramp generator in the turbine control loop. The ramp generator was replaced and the control loop functionally tested to ensure proper operation. The mode of failure of the ramp generator would have been detected during routine operability testing due to the inability to move the turbine control valve to positions greater than 40% open.

FACILITY STATUS: E (28) | % POWER: 0 3 3 (29) | OTHER STATUS (30): NA | METHOD OF DISCOVERY: B (31) | DISCOVERY DESCRIPTION (32): Operator Observation

ACTIVITY RELEASED: Z (33) | CONTENT OF RELEASE: Z (34) | AMOUNT OF ACTIVITY (35): NA | LOCATION OF RELEASE (36): NA

PERSONNEL EXPOSURES — NUMBER: 0 0 0 (37) | TYPE: Z (38) | DESCRIPTION (39): NA

PERSONNEL INJURIES — NUMBER: 0 0 0 (40) | DESCRIPTION (41): NA

LOSS OF OR DAMAGE TO FACILITY — TYPE: Z (42) | DESCRIPTION: NA

PUBLICITY — ISSUED: N (43) | DESCRIPTION (45): NA

1033 320

7909280 416

NRC USE ONLY

NAME OF PREPARER: R. T. Nix

PHONE: 912-367-7781