NRC FORM 366
(7-77)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

LER 79-25/1P

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 VTVYS1 (2) 00-0000-00 (3) 41111 (4) (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 REPORT SOURCE L (6) 05000271 (7) 103079 (8) 103079 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While performing refuel outage associated inspection of 8x8R fuel assemblies, evidence
03 of end plug wear was discovered on the water rods associated with both assemblies.
04 Examination of fuel rods located in the general area of the water rods revealed no
05 indication of end plug wear.
06
07
08

09 SYSTEM CODE RC (11) CAUSE CODE E (12) CAUSE SUBCODE B (13) COMPONENT CODE FUELXX (14) COMP. SUBCODE Z (15) VALVE SUBCODE Z (16)

(17) LER RO REPORT NUMBER: EVENT YEAR 79 — SEQUENTIAL REPORT NO. 025 — OCCURRENCE CODE 01 — REPORT TYPE P — REVISION NO. 0

ACTION TAKEN Z (18) FUTURE ACTION Z (19) EFFECT ON PLANT Z (20) SHUTDOWN METHOD Z (21) HOURS 0000 (22) ATTACHMENT SUBMITTED N (23) NPRD-4 FORM SUB. Y (24) PRIME COMP. SUPPLIER Y (25) COMPONENT MANUFACTURER G080 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10
11 The cause of the wear is unknown at present. An evaluation will be made, along with
12 corrective action if deemed necessary in a subsequent report.
13
14

15 FACILITY STATUS H (28) % POWER 000 (29) OTHER STATUS (30) NA METHOD OF DISCOVERY C (31) DISCOVERY DESCRIPTION (32) Fuel Assembly Inspection

16 ACTIVITY RELEASED Z (33) CONTENT OF RELEASE Z (34) AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36) NA

17 PERSONNEL EXPOSURES NUMBER 000 (37) TYPE (38) DESCRIPTION (39) NA

18 PERSONNEL INJURIES NUMBER 000 (40) DESCRIPTION (41) NA

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) DESCRIPTION (43) NA

20 PUBLICITY ISSUED N (44) DESCRIPTION (45) NA

NRC USE ONLY

1076 087

79101 10308

NAME OF PREPARER W. F. Conway PHONE 802-257-7711