NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

EXHIBIT A

LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| 0 | 1 | F L C R P 3 (2) 0 0 - 0 0 0 0 0 - 0 0 (3) 4 1 1 1 1 (4) - - (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T | 0 | 1 | REPORT SOURCE L (6) 0 5 0 - 0 3 0 2 (7) 0 9 2 7 7 9 (8) 1 0 1 9 7 9 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

| 0 | 2 | At 1309 in Mode 1, it was reported that "B" OTSG blowdown isolation valve
| 0 | 3 | MSV-148 was not properly tested prior to being returned to service. This
| 0 | 4 | created an event contrary to Technical Specification 4.6.3.1. No effect upon
| 0 | 5 | the plant or general public. MSV-148 was placed in the closed position. This
| 0 | 6 | is the first occurrence of this type reported for MSV-148.
| 0 | 7 |
| 0 | 8 |

	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP SUBCODE	VALVE SUBCODE
0 9	Z Z (11)	Z (12)	Z (13)	Z Z Z Z Z Z (14)	Z (15)	Z (16)

(17) LER/RO REPORT NUMBER

EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
7 9	-	0 9 4	/	0 3	L	-	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
G (18)	Z (19)	Z (20)	Z (21)	0 0 0 0	Y (23)	N (24)	Z (25)	Z 9 9 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

| 1 | 0 | The cause of this event is attributed to defective procedures. Surveillance
| 1 | 1 | Procedures did not contain provisions for testing MSV-148. A review of Sur-
| 1 | 2 | veillance Procedures has been conducted to determine generic implications .
| 1 | 3 | Applicable procedures will be revised to include provisions per testing Tech-
| 1 | 4 | nical Specification-related valves.

	FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
1 5	E (28)	1 0 0 (29)	NA	B (31)	Operation observation

	ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
1 6	Z (33)	Z (34)	NA	NA

PERSONNEL EXPOSURES

	NUMBER	TYPE	DESCRIPTION (39)
1 7	0 0 0 (37)	Z (38)	NA

PERSONNEL INJURIES

	NUMBER	DESCRIPTION (41)
1 8	0 0 0 (40)	NA

POOR ORIGINAL

1229 098

LOSS OF OR DAMAGE TO FACILITY (43)

	TYPE	DESCRIPTION
1 9	Z (42)	NA

PUBLICITY

	ISSUED	DESCRIPTION (45)	NRC USE ONLY
2 0	N (44)	NA	

NAME OF PREPARER J. Cooper PHONE (904) 795-6486

(SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET)

7910300353

SUPPLEMENTARY INFORMATION

Report No.: 50-302/79-094/03L-0

Facility: Crystal River Unit #3

Report Date: 19 October 1979

Occurrence Date: 27 September 1979

Identification of Occurrence:

Failure to perform post maintenance testing of "B" OTSG blowdown valve MSV-148 contrary to Technical Specification 4.6.3.1.

Conditions Prior to Occurrence:

Mode 1 power operation 100%.

Description of Occurrence:

At 1309 it was reported that "B" OTSG blowdown isolation valve MSV-148 was not properly tested prior to being returned to service, following maintenance conducted on 2 July 1979. MSV-148 was returned to service at 1105 on 28 September 1979 following completion of appropriate post maintenance testing.

Designation of Apparent Cause:

The cause of this event is attributed to defective procedures. Surveillance Procedures did not contain provisions for testing MSV-148.

Analysis of Occurrence:

No effect upon the plant or general public. MSV-148 was placed in the closed position.

Corrective Action:

A review of Surveillance Procedures has been conducted to determine generic implications. Applicable procedures will be revised to include provisions for testing Technical Specification-related valves.

Failure Data:

This is the first occurrence of this type reported for MSV-148.

1229 099

/rc