NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: ☐☐☐☐☐☐ ①   (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | LICENSEE CODE: F L C R P 3 ② | LICENSE NUMBER: 0 0 - 0 0 0 0 0 - 0 0 ③ | LICENSE TYPE: 4 1 1 1 1 ④ | CAT: - - ⑤

CON'T
0 1 | REPORT SOURCE: L ⑥ | DOCKET NUMBER: 0 5 0 - 0 3 0 2 ⑦ | EVENT DATE: 1 2 0 8 7 8 ⑧ | REPORT DATE: 1 2 2 9 7 8 ⑨

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

0 2 At 1430, while performing Surveillance Procedure SP-345, Auxiliary Building
0 3 Ventilation Exhaust System Monthly Test, low flow and imbalance fan loads
0 4 were experienced. This is contrary to Tech Spec. 3.7.8.1. Operability
0 5 was restored within two hours. No effects upon public health and safety as
0 6 negative pressure was maintained in the Auxiliary Building and a redundant
0 7 system was available and operable. Six previous occurrences reported,
0 8 first reported event of this type.

	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP SUBCODE	VALVE SUBCODE
0 9	A A ⑪	X ⑫	Z ⑬	L O W E R ⑭	Z ⑮	Z ⑯

⑰ LER RO REPORT NUMBER	EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
	7 8	—	0 6 6	/	0 3	L	—	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS ㉒	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB	PRIME COMP SUPPLIER	COMPONENT MANUFACTURER
Z ⑱	Z ⑲	Z ⑳	Z ㉑	0 0 0 0	Y ㉓	N ㉔	A ㉕	J 1 2 7 ㉖

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ㉗

1 0 The cause of this event cannot be determined, as normal operation and air
1 1 flow returned during the initial investigation by Operations personnel.
1 2 No corrective action taken as system operability restored itself and the
1 3 described condition has not recurred.
1 4

	FACILITY STATUS	% POWER	OTHER STATUS ㉚	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION ㉜
1 5	E ㉘	0 9 5 ㉙	NA	A ㉛	Operator observation

	ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY ㉟	LOCATION OF RELEASE ㊱
1 6	Z ㉝	Z ㉞	NA	NA

	PERSONNEL EXPOSURES NUMBER	TYPE	DESCRIPTION ㊴
1 7	0 0 0 ㊲	Z ㊳	NA

	PERSONNEL INJURIES NUMBER	DESCRIPTION ㊶
1 8	0 0 0 ㊵	NA

	LOSS OF OR DAMAGE TO FACILITY ㊸ TYPE	DESCRIPTION
1 9	Z ㊷	NA

	PUBLICITY ISSUED	DESCRIPTION ㊺	NRC USE ONLY
2 0	N ㊹	NA	☐☐☐☐☐☐☐☐☐☐☐☐

NAME OF PREPARER JC J. Cooper   PHONE (904) 795-6486

(SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET)

7901090187

SUPPLEMENTARY INFORMATION

Report No.: 50-302/78-066/03L-0

Facility: Crystal River Unit #3

Report Date: 29 December 1978

Occurrence Date: 8 December 1978

Identification of Occurrence:

One pair of Auxiliary Building exhaust ventilation fans inoperable contrary to Technical Specification 3.7.8.1.

Conditions Prior to Occurrence:

Mode 1 (95%).

Description of Occurrence:

At 1430, while performing Surveillance Procedure SP-345, Auxiliary Building Ventilation Exhaust System Monthly Test, low air flow and imbalanced fan loads were experienced while operating AHF-14B & 14D, Auxiliary Building exhaust fans. An Auxiliary Building supply fan AHF-11a was secured to prevent positive pressures within the Auxiliary Building. Normal air flow and fan operability was restored within two hours.

Designation of Apparent Cause:

The cause of this event cannot be determined as normal operation and air flow returned during the initial investigation by Operations personnel.

Analysis of Occurrence:

There was no hazard to plant or general public as negative pressures were maintained within the Auxiliary Building and a redundant fan system was available and operable.

Corrective Action:

No corrective action taken as system operability restored itself. As a result of a later investigation of the Auxiliary Building ventilation exhaust system, damper #34 in the Spent Fuel area exhaust was found about 85% closed.

Failure Data:

Six previously reported occurrences, but first reported event of this type.

/rc