ITT Grinnell
Industrial Piping, Inc.

P. O. Box 566
Kernersville, N. C. 27284
(919) – 993-4831
Telex No.: 806439

November 16, 1979

United States Nuclear Regulatory Commission
Region IV
611 Ryan Drive Suite 1000
Arlington, Texas 76011

Attention: Uldis Potapous,
Chief Vendor Inspection Branch

Subject: Inspection Response Docket No. 99900019/79-01

Dear Sir:

Responding to your letter of October 17, 1979 questioning the resolution of corrective action on Item D dealing with the re-testing of pipe for impact properties.

As indicated by previous letters, the complete piping system was being reviewed with the Piping Designers for the involved project (Bechtel Power Corporation).

Resultant of this review, the original + 30°F test temperature was determined to be unnecessarily low and changed for the system involved to + 70°F by the Design Engineers. With this new test temperature, retests were performed and satisfactory results were obtained.

We apologize for the delay in the final corrective action; however, in order to complete the review and obtain the Piping Designers' information as well as the retesting, the time was required.

If I can provide further information, please do not hesitate to contact the writer.

Very truly yours,

E. P. Johnson

1616 110

Emil Johnson
Director of Quality Assurance

EJ:dg
cc: W. C. Amidon

7912260 104