MAINE YANKEE ATOMIC POWER COMPANY
ENGINEERING OFFICE
TURNPIKE ROAD (RT. 9)
WESTBORO, MASSACHUSETTS 01581
617-366-9011

B.4.1.1
WMY 80-5

January 9, 1980

United States Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, PA 19406

Attention: Mr. Boyce H. Grier
Director

References:
(a) License No. DPR-36 (Docket No. 50-309)
(b) USNRC Letter to MYAPC dated March 8, 1979
I&E Bulletin 79-02
(c) USNRC Letter to MYAPC dated June 21, 1979
I&E Bulletin 79-02, Revision 1
(d) MYAPC Letter to USNRC dated July 5, 1979
(e) MYAPC Letter to USNRC dated October 11, 1979
(f) MYAPC Letter to USNRC dated November 14, 1979
(g) USNRC Letter to MYAPC dated November 8, 1979
I&E Bulletin 79-02, Revision 2
(h) USNRC Letter to MYAPC dated November 21, 1979

Gentlemen:

Subject: Maine Yankee I&E Bulletin 79-02

The following statements are made in response to I&E Bulletin 79-02 Revision 2, Reference (g):

a. No seismic piping restraints at Maine Yankee are supported by anchor bolts in concrete block walls.
b. Our inspection/testing program for anchor bolts considered all expansion type anchor bolts without regard for the configuration of support structure between building structure and pipe.

In addition, Reference (g) requested justification of our sampling program which was provided previously in Reference (f).

8002150 484

We trust this response fulfills your current requirements on this subject. If, however, you desire additional information, please contact us at your convenience.

Sincerely,

MAINE YANKEE ATOMIC POWER COMPANY

for D. E. Moody
Manager of Operations

MMA/nj