ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

March 22, 1979

2-039-10

Mr. K. V. Seyfrit, Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

Subject: Arkansas Nuclear One - Unit 2
Docket No. 50-368
License No. NPF-6
Reportable Occurrence Report
Nos. 50-368/78-13 (Rev. 1);
50-368/78-15 (Rev. 1);
50-368/79-19 and 50-368/79-20
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specifications 6.9.1.8 and 6.9.1.9, we have attached the subject reports involving the resubmittal of two 1978 ROR's concerning a design problem in a speed switch on the "B" Emergency Diesel Generator that was incorrectly identified on the original submittal as the "A" generator (78-13); the failure to perform surveillance testing as required by Technical Specifications submitted originally as a 30-day report but now being re-evaluated as a 14-day type report (78-15); the inoperability of a Main Steam line safety valve (79-19); and the breaking of a warning lockpin on the Main Steam safety valve (79-20).

50-368/79-19 and 50-368/79-20 are being submitted late after conversations and decisions between the I&E on-site inspector and plant staff. These reports are submitted late with the concurrence of the on-site inspector.

Very truly yours,

David C. Trimble

David C. Trimble
Manager, Licensing

DCT:REI:lg

Attachments

7903270469

S

CC: Mr. Norman M. Haller, Director
Office of Management and
Program Analysis
U. S. Nuclear Regulatory
Commission
Washington, D.C. 20555

Mr. W. D. Johnson
U. S. Nuclear Regulatory
Commission
P. O. Box 2090
Russellville, Arkansas 72801

Mr. John G. Davis, Acting Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory
Commission
Washington, D. C. 20555