LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] (1–6) (PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME	LICENSE NUMBER	LICENSE TYPE	EVENT TYPE
FLCRP3 (7–9, 10–14)	00-00000-00 (15–25)	4111 1 (26–30)	01 (31–32)

01 CONT

CATEGORY	REPORT TYPE	REPORT SOURCE	DOCKET NUMBER	EVENT DATE	REPORT DATE
00 (57–58)	0 (59)	L (60)	050-0302 (61–68)	121776 (69–74)	020277 (75–80)

EVENT DESCRIPTION

02 During trouble shooting of Emergency Safeguards Actuation System, high pressure
03 injection was inadvertently actuated. System drawing error was cause and appro-
04 priate design change request has been initiated. Because of RC System condition,
05 this is considered to be the zero (0) cycle HPI.
06 (77-7)

SYSTEM CODE	CAUSE CODE	COMPONENT CODE	PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER	VIOLATION
07 SF (10)	B (11)	INSTRU (12–17)	A (43)	XXXX (44–47)	N (48)

CAUSE DESCRIPTION

08 Design drawing showed incorrect channel designation. Design change has been
09 requested to correct channel feed designation.
10

FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
11 B (9)	000 (10–12)	Mode 5 (13–44)	A (45)	Alarm (46–80)

FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
12 (9)	(10)	N/A (11–44)	(45–80)

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION
13 (11)	(12)	N/A (13–80)

PERSONNEL INJURIES

NUMBER	DESCRIPTION
14 (11)	N/A (12–80)

OFFSITE CONSEQUENCES

15 N/A

LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION
16 (10)	N/A (10–80)

PUBLICITY

17 N/A

ADDITIONAL FACTORS

N/A

19 8002270591

NAME: W. P. Stewart LUPS PHONE: (813) 866-4159

GPO 881-667