LICENSEE EVENT REPORT

CONTROL BLOC [ ] (1–6) (PLEASE PRINT ALL REQUIRED INFORMATIO

	LICENSEE NAME	LICENSE NUMBER	LICENSE TYPE	EVENT TYPE
	FLCRP3 (7–14)	00–00000–00 (15–25)	4111 (26–30)	03 (31–32)

	CATEGORY	REPORT TYPE	REPORT SOURCE	DOCKET NUMBER	EVENT DATE	REPORT DATE
01 CONT	- - (57–58)	L (59)	L (60)	05000–0302 (61–68)	070277 (69–74)	070287 (75–)

EVENT DESCRIPTION

02 In mode 2 operation while performing operability test of rod 3 group 6 API, the absolute
03 position indication for all regulating rods was lost, creating a condition as defined
04 by Tech Spec 3.0.3. Redundancy was maintained with the relative position indication.
05 This was a non-repetitive occurrence. Maintenance restored the API system operable
06 within 8 minutes. (LER 77-75)

	SYSTEM CODE	CAUSE CODE	COMPONENT CODE	PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER	VIOLATION
07	ID (10)	F (11)	INSTRU (12–17)	N (43)	D150 (44–47)	N (48)

CAUSE DESCRIPTION

08 The 15 volt power supplies for the API system crowbarred due to a spike of unknown
09 origin and were reset restoring system operability.
10

	FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
11	C (9)	000 (10–12)	NA (13–44)	A (45)	NA (46–)

	FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
12	Z (9)	Z (10)	NA (11–44)	NA (45–)

PERSONNEL EXPOSURES

	NUMBER	TYPE	DESCRIPTION
13	000 (11–12)	Z (13)	NA

PERSONNEL INJURIES

	NUMBER	DESCRIPTION
14	000 (11–12)	NA

OFFSITE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

	TYPE	DESCRIPTION
16	Z (10)	NA

PUBLICITY

17 NA

ADDITIONAL FACTORS

See attached Supplementary Information

18

8002280987

NAME: W. P. Stewart PHONE: (813) 866-4159

GPO 884-667

SUPPLEMENTARY INFORMATION

1. Report No.: 50-302/77-75

2. Facility: Crystal River Unit #3

3. Report Date: 28 July 1977

4. Occurrence Date: 2 July 1977

5. Identification of Occurrence:

The loss of all absolute position indication resulted in a limiting condition for operation in excess of those addressed in the Specifications as defined by Technical Specification 3.0.3.

6. Conditions Prior to Occurrence:

Mode 2 startup operation.

7. Description of Occurrence:

At 0435 while performing operability test of the absolute position indication of rod 3 of group 6, the absolute position indication for all rods was lost. The Electrical Supervisor was immediately notified and preparations were made to go to hot standby within 1 hour, as required by Technical Specifications. The absolute position indication system was restored operable within 8 minutes.

8. Designation of Apparent Cause:

An apparent spike from an unknown origin caused a crowbar of the API 15 volt power supplies. The power supplies were reset and the API system restored operable.

9. Analysis of Occurrence:

There were no safety implications as a result of this occurrence.

10. Corrective Action:

No corrective action deemed necessary as normal maintenance restored system operability.

11. Failure Data:

This was not a repetitive occurrence.