(7-77)

LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1	M D C C N 2 (2)	0 0 - 0 0 0 0 0 - 0 0 (3)	4 1 1 1 1 (4)	(5)		
	LICENSEE CODE	LICENSE NUMBER	LICENSE TYPE	CAT		
CON'T 0 1	REPORT SOURCE L (6)	0 5 0 0 0 3 1 8 (7)	0 3 1 2 8 0 (8)	0 3 2 5 8 0 (9)		
		DOCKET NUMBER	EVENT DATE	REPORT DATE		

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While performing a Quality Control Inspection in the Unit 2 cable spreading
0 3 room, it was found that Cable #A2y0929P was incorrectly routed from 2R01A to
0 4 cable tray #ZB2AG13 and then back to its proper cable tray #ZA2AH03, thus
0 5 violating the cable separation criteria by crossing from a ZB to ZA facility.
0 6 This is not a repetitive occurrence.
0 7
0 8

	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
0 9	Z Z (11)	A (12)	E (13)	Z Z Z Z Z Z (14)	Z (15)	Z (16)

(17) LER/RO REPORT NUMBER	EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
	8 0	—	0 1 9	/	0 2	L	—	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
X (18)	Z (19)	Z (20)	Z (21)	0 0 0 0	N (23)	N (24)	Z (25)	Z 9 9 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Construction personnel did not follow the designed routing of cable #A2Y0929P.
1 1 The interim corrective action was to install a temporary cable from 2R01A to
1 2 2Y09 and deenergize the incorrectly installed cable. The temporary cable will
1 3 be replaced by a permanent cable in the correct routing in the immediate future.
1 4

	FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
1 5	E (28)	0 9 6 (29)	NA	C (31)	Q.C. Inspection of Work on FCR 79-1034

	ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
1 6	Z (33)	Z (34)	NA	NA

PERSONNEL EXPOSURES

	NUMBER	TYPE	DESCRIPTION (39)
1 7	0 0 0 (37)	Z (38)	NA

PERSONNEL INJURIES

	NUMBER	DESCRIPTION (41)
1 8	0 0 0 (40)	NA

LOSS OF OR DAMAGE TO FACILITY (43)

	TYPE	DESCRIPTION
1 9	Z (42)	NA

PUBLICITY

	ISSUED	DESCRIPTION (45)	NRC USE ONLY
2 0	N (44)	NA	

NAME OF PREPARER E. R. Bauer PHONE: (301)269-4728

8004010383

GPO 917-926