THIS DOCUMENT CONTAINS POOR QUALITY PAGES

8005200 582

NRC FORM 366 (7-77)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | T N S N P 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T 01 | REPORT SOURCE L (6) | 0 5 0 0 0 3 2 7 (7) | 0 4 2 8 8 0 (8) | 0 5 0 9 8 0 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During the performance of Surveillance Instruction 26, it was
03 discovered that two interface temporary alteration control forms (TACF's)
04 had been placed on the wrong cables. These interface TACF's were to
05 prevent auto start of the Aux. Building Gas Treatment system from a U-2
06 containment isolation. However, cables for U-1 were tagged and lifted
07 disabling U-1 ABGTS in the event of a U-1 containment isolation.
08

09 | SYSTEM CODE: X X (11) | CAUSE CODE: X (12) | CAUSE SUBCODE: X (13) | COMPONENT CODE: X X X X X X (14) | COMP. SUBCODE: Z (15) | VALVE SUBCODE: Z (16)

(17) LER/RO REPORT NUMBER | EVENT YEAR: 8 0 | — | SEQUENTIAL REPORT NO.: 0 3 7 | / | OCCURRENCE CODE: 0 3 | REPORT TYPE: L | — | REVISION NO.: 0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
X (18)	Z (19)	Z (20)	Z (21)	0 0 0 0	N (23)	N (24)	Z (25)	Z 9 9 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Cables from U-1 & U-2 containment isolation relay contacts terminate
11 on the same terminal block points to initiate the ABGTS. In an attempt
12 to disconnect U-2 cables for Pre-op testing, U-1 cables were lifted and
13 TACF's installed. U-1 cables have been reterminated and U-2 lifted and
14 tagged.

15 | FACILITY STATUS: B (28) | % POWER: 0 0 0 (29) | OTHER STATUS (30): NA | METHOD OF DISCOVERY: B (31) | DISCOVERY DESCRIPTION (32): Surveillance Instruction 26

16 | ACTIVITY RELEASED: Z (33) | CONTENT OF RELEASE: Z (34) | AMOUNT OF ACTIVITY (35): NA | LOCATION OF RELEASE (36): NA

PERSONNEL EXPOSURES
17 | NUMBER: 0 0 0 (37) | TYPE: Z (38) | DESCRIPTION (39): NA

PERSONNEL INJURIES
18 | NUMBER: 0 0 0 (40) | DESCRIPTION (41): NA

LOSS OF OR DAMAGE TO FACILITY (43)
19 | TYPE: Z (42) | DESCRIPTION: NA

PUBLICITY
20 | ISSUED: N (44) | DESCRIPTION (45): NA | NRC USE ONLY

NAME OF PREPARER Walter A. Watson PHONE:

8005200582

NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: [| | | | |] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 LICENSEE CODE: T N S N P 1 (2) LICENSE NUMBER: 0 0 - 0 0 0 0 0 - 0 0 (3) LICENSE TYPE: 4 1 1 1 1 (4) CAT: (5)

CON'T 01 REPORT SOURCE: L (6) DOCKET NUMBER: 0 5 0 0 0 3 2 7 (7) EVENT DATE: 0 4 2 8 8 0 (8) REPORT DATE: 0 5 0 9 8 0 (9)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During the performance of Surveillance Instruction 26, it was
03 discovered that two interface temporary alteration control forms (TACF's)
04 had been placed on the wrong cables. These interface TACF's were to
05 prevent auto start of the Aux. Building Gas Treatment system from a U-2
06 containment isolation. However, cables for U-1 were tagged and lifted
07 disabling U-1 ABGTS in the event of a U-1 containment isolation.
08

09 SYSTEM CODE: X X (11) CAUSE CODE: X (12) CAUSE SUBCODE: X (13) COMPONENT CODE: X X X X X X (14) COMP. SUBCODE: Z (15) VALVE SUBCODE: Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR: 8 0 — SEQUENTIAL REPORT NO.: 0 3 7 / OCCURRENCE CODE: 0 3 REPORT TYPE: L — REVISION NO.: 0

ACTION TAKEN: X (18) FUTURE ACTION: Z (19) EFFECT ON PLANT: Z (20) SHUTDOWN METHOD: Z (21) HOURS (22): 0 0 0 0 ATTACHMENT SUBMITTED: N (23) NPRD-4 FORM SUB.: N (24) PRIME COMP. SUPPLIER: Z (25) COMPONENT MANUFACTURER: Z 9 9 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Cables from U-1 & U-2 containment isolation relay contacts terminate
11 on the same terminal block points to initiate the ABGTS. In an attempt
12 to disconnect U-2 cables for Pre-op testing, U-1 cables were lifted and
13 TACF's installed. U-1 cables have been reterminated and U-2 lifted and
14 tagged.

15 FACILITY STATUS: B (28) % POWER: 0 0 0 (29) OTHER STATUS (30): NA METHOD OF DISCOVERY: B (31) DISCOVERY DESCRIPTION (32): Surveillance Instruction 26

16 ACTIVITY RELEASED: Z (33) CONTENT OF RELEASE: Z (34) AMOUNT OF ACTIVITY (35): NA LOCATION OF RELEASE (36): NA

PERSONNEL EXPOSURES
17 NUMBER: 0 0 0 (37) TYPE: Z (38) DESCRIPTION (39): NA

PERSONNEL INJURIES
18 NUMBER: 0 0 0 (40) DESCRIPTION (41): NA

LOSS OF OR DAMAGE TO FACILITY (43)
19 TYPE: Z (42) DESCRIPTION: NA

PUBLICITY
20 ISSUED: N (44) DESCRIPTION (45): NA

NRC USE ONLY

NAME OF PREPARER: Walter A. Watson PHONE: