THIS DOCUMENT CONTAINS
POOR QUALITY PAGES

TENNESSEE VALLEY AUTHORITY
CHATTANOOGA, TENNESSEE 37401
1750 Chestnut Street Tower II

June 10, 1980

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET NO. 50-327 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE REPORT SQRO-50-327/8057

The enclosed report provides details concerning the sense line for PT-68-340 which blew loose at a compression fitting taking that channel out-of-service and leaving less than three operable channels for monitoring pressurizer pressure. This report is submitted in accordance with Sequoyah unit 1 Technical Specification 6.9.1.13.b.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. R. Calhoun
Director of Nuclear Power

Enclosure (3)
cc (Enclosure):
Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. Bill Lavallee
Nuclear Safety Analysis Center
Palo Alto, California 94303

Mr. W. T. Cottle, NRC Inspector, Sequoyah

A002
S. 1/1

8006170 554

An Equal Opportunity Employer

3