APPENDIX A

NOTICE OF DEVIATION

Northern States Power Company

License No. DPR-42
DPR-60

Based on the results of an NRC inspection conducted during the period April 1-30, 1980, it appears that one of your activities was not conducted in conformance with your commitments to the Commission as indicated below.

Your responses to IE Bulletin No. 78-05, dated May 30, 1978 and August 22, 1979, commit that the special inspections of plunger arm clearance on motor starters on safety related systems would be completed during the next refueling outage. Both units have subsequently completed refueling outages.

Contrary to the above, the special inspections had not been completed for the motor starters associated with the power operated relief valve isolation valves for either unit.

8007070 056