NRC FORM 366
(7-77)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

LER 80-12/1P

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7–8	9–14 LICENSEE CODE	15–25 LICENSE NUMBER	26–30 LICENSE TYPE	31–32 CAT
01	VTVYS1 (2)	00-00000-00 (3)	41111 (4)	(5)

CON'T

7–8	60 REPORT SOURCE	61–68 DOCKET NUMBER	69–74 EVENT DATE	75–80 REPORT DATE
01	L (6)	05000271 (7)	032880 (8)	032880 (9)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During the seismic analyses to determine the adequacy of seismic supports as required
03 by NRC letter of 10/24/79 and Bulletin 79-14, it was discovered that pipe supports
04 RHR-H-83 and RSW-H-168 may be inadequate to support their seismic load as manufactured.
05 In accordance with this letter, required modifications will be completed within 7 days.
06 Engineering evaluations have determined that system components are not inoperable.
07 Previous failures were reported as RO 79-33/1P and 34/1P.
08
09

7–8	9–10 SYSTEM CODE	11–12 CAUSE CODE	13 CAUSE SUBCODE	14–18 COMPONENT CODE	19 COMP SUBCODE	20 VALVE SUBCODE
09	XX (11)	B (12)	B (13)	SCPORT (14)	X (15)	Z (16)

(17) LER RO REPORT NUMBER	21–22 EVENT YEAR	23	24–26 SEQUENTIAL REPORT NO.	27	28–29 OCCURRENCE CODE	30 REPORT TYPE	31	32 REVISION NO.
	80	—	012	/	01	P	—	0

33–34 ACTION TAKEN	35 FUTURE ACTION	36 EFFECT ON PLANT	37 SHUTDOWN METHOD	38–40 HOURS (22)	41 ATTACHMENT SUBMITTED	42 NPRD-4 FORM SUB	43 PRIME COMP SUPPLIER	44–47 COMPONENT MANUFACTURER
B (18)	Z (19)	Z (20)	Z (21)	0000	Y (23)	Y (24)	A (25)	1207 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause of this event is deviations from the hanger design details. Appropriate
11 modifications to the subject pipe support systems will be performed to insure that
12 the systems meet the requirements of our seismic analysis.
13
14

7–8	9 FACILITY STATUS	10–12 % POWER	13–44 OTHER STATUS (30)	45 METHOD OF DISCOVERY	46–80 DISCOVERY DESCRIPTION (32)
15	E (28)	100 (29)	NA	C (31)	Investigation relating to NRC Bull. 79-14

7–8	9 ACTIVITY RELEASED	10 CONTENT OF RELEASE	11–44 AMOUNT OF ACTIVITY (35)	45–80 LOCATION OF RELEASE (36)
16	Z (33)	Z (34)	NA	NA

PERSONNEL EXPOSURES

7–8	9–11 NUMBER	12 TYPE	13–80 DESCRIPTION (39)
17	000 (37)	Z (38)	NA

PERSONNEL INJURIES

7–8	9–11 NUMBER	12–80 DESCRIPTION (41)
18	000 (40)	NA

LOSS OF OR DAMAGE TO FACILITY (43)

7–8	9 TYPE	10–80 DESCRIPTION
19	Z (42)	NA

8004020362

PUBLICITY

7–8	9 ISSUED	10–68 DESCRIPTION (45)	69–80 NRC USE ONLY
20	N (44)	NA	

POOR ORIGINAL

NAME OF PREPARER H. D. Murphy PHONE: 802-257-7711