NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | C | A | R | S | S | 1 | (2) | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | (3) | 4 | 1 | 1 | 1 | 1 | (4) | | | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 REPORT SOURCE | L | (6) | 0 | 5 | 0 | 0 | 3 | 1 | 2 | (7) | 0 | 5 | 0 | 2 | 8 | 1 | (8) | 0 | 6 | 0 | 2 | 8 | 1 | (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On May 2, 1981, while performing S2 204.03A, Quarterly RBS System A Loop
03 Surveillance and Inservice Test, the RBS pump breaker, 3A09, tripped when
04 a start was attempted from the control room. The trip signals (86 Lockout
05 and bell alarm) were reset and a second start attempt from the control room
06 was successful. The surveillance test was completed with satisfactory
07 results.
08

09 SYSTEM CODE | S | H | (11) CAUSE CODE | X | (12) CAUSE SUBCODE | Z | (13) COMPONENT CODE | C | K | T | B | R | K | (14) COMP. SUBCODE | F | (15) VALVE SUBCODE | Z | (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR | 8 | 1 | — | SEQUENTIAL REPORT NO. | 0 | 2 | 7 | / | OCCURRENCE CODE | 0 | 3 | REPORT TYPE | L | — | REVISION NO. | 0 |

ACTION TAKEN | X | (18) FUTURE ACTION | Z | (19) EFFECT ON PLANT | Z | (20) SHUTDOWN METHOD | Z | (21) HOURS (22) | 0 | 0 | 0 | 0 | ATTACHMENT SUBMITTED | Y | (23) NPRDS FORM SUB. | N | (24) PRIME COMP. SUPPLIER | A | (25) COMPONENT MANUFACTURER | 1 | 0 | 0 | 5 | (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 After resetting the trip subsequent start attempts were successful. The
11 problem could not be repeated. In rush current measurements were taken and
12 were found to be well below the instantaneous overcurrent trip values. No
13 definate cause for the occurrence could be determined. Unless a similar
14 recurrence is experienced no further corrective action is planned.

15 FACILITY STATUS | H | (28) % POWER | 0 | 0 | 0 | (29) OTHER STATUS (30) | N/A | METHOD OF DISCOVERY | B | (31) DISCOVERY DESCRIPTION (32) | Routine Surveillance

16 ACTIVITY RELEASED | Z | (33) CONTENT OF RELEASE | Z | (34) AMOUNT OF ACTIVITY (35) | N/A | LOCATION OF RELEASE (36) | N/A

17 PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | (37) TYPE | Z | (38) DESCRIPTION (39) | N/A

18 PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | (40) DESCRIPTION (41) | N/A

19 LOSS OF OR DAMAGE TO FACILITY TYPE | Z | (42) DESCRIPTION (43) | N/A

20 PUBLICITY ISSUED | Y | (44) DESCRIPTION (45) | Local newspapers and wire services | NRC USE ONLY

8106090560

NAME OF PREPARER R. W. Colombo PHONE (916) 452-3211