NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

Line	Field	Entry
0 1	LICENSEE CODE (2)	F L C R P 3
	LICENSE NUMBER (3)	0 0 - 0 0 0 0 0 - 0 0
	LICENSE TYPE (4)	4 1 1 1 1
	CAT (5)	
CON'T 0 1	REPORT SOURCE (6)	L
	DOCKET NUMBER (7)	0 5 0 - 0 3 0 2
	EVENT DATE (8)	0 8 1 2 8 2
	REPORT DATE (9)	

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 At 1000, during daily operating surveillance, it was discovered that
0 3 one remote reactor coolant temperature indicator, (RC-4A-TI2) was
0 4 inoperable. This is contrary to the requirements of T.S. 3.3.3.5.
0 5 Operability was restored at 1505 on 8/12/82. Temperature indication for
0 6 the other reactor coolant loop was available through operable indicator
0 7 RC-4B-TI2. There was no effect upon public health or safety. This is the
0 8 3rd occurrence for this instrument and the 11th report under this spec.

0 9	SYSTEM CODE (11)	CAUSE CODE (12)	CAUSE SUBCODE (13)	COMPONENT CODE (14)	COMP SUBCODE (15)	VALVE SUBCODE (16)
	I C	X	Z	I N S T R U	I	Z

(17) LER/RO REPORT NUMBER	EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
	8 2	—	0 5 4	/	0 3	L	—	0

ACTION TAKEN (18)	FUTURE ACTION (19)	EFFECT ON PLANT (20)	SHUTDOWN METHOD (21)	HOURS (22)	ATTACHMENT SUBMITTED (23)	NPRD-4 FORM SUB. (24)	PRIME COMP. SUPPLIER (25)	COMPONENT MANUFACTURER
X	Z	Z	Z	0 0 0 0	Y	N	A	B 0 4 5

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of this event was dirty terminals. The instrument lugs and
1 1 terminals were cleaned and the instrument was determined OPERABLE.
1 2 No further corrective action is considered necessary.
1 3
1 4

1 5	FACILITY STATUS (28)	% POWER (29)	OTHER STATUS (30)	METHOD OF DISCOVERY (31)	DISCOVERY DESCRIPTION (32)
	E	0 9 5	NA		OPERATOR OBSERVATION

1 6	ACTIVITY RELEASED (33)	CONTENT OF RELEASE (34)	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
	Z	Z	NA	NA

PERSONNEL EXPOSURES

1 7	NUMBER (37)	TYPE (38)	DESCRIPTION (39)
	0 0 0	Z	NA

PERSONNEL INJURIES

1 8	NUMBER (40)	DESCRIPTION (41)
	0 0 0	NA

LOSS OF OR DAMAGE TO FACILITY (43)

1 9	TYPE (42)	DESCRIPTION
	Z	NA

PUBLICITY

2 0	ISSUED (44)	DESCRIPTION (45)	NRC USE ONLY
	N	NA	

NAME OF PREPARER E.W. Ford PHONE (904) 795-6486

8209160447 820910
PDR ADOCK 05000302
S PDR

SUPPLEMENTARY INFORMATION

REPORT NO: 50-302/82-054/03L-0

FACILITY: Crystal River Unit #3

REPORT DATE: September 10, 1982

OCCURRENCE DATE: August 12, 1982

IDENTIFICATION OF OCCURRENCE:

Remote Reactor Coolant Temperature Instrument was inoperable contrary to Technical Specification 3.3.3.5.

CONDITIONS PRIOR TO OCCURRENCE:

Mode 1 Power Operation (95%).

DESCRIPTION OF OCCURRENCE:

At 1000 during performance of SP-300,"Operating Daily Surveillance Log," it was discovered that Remote Reactor Coolant Temperature Instrument, RC-4A-TI2, was inoperable. Maintenance was initiated and operability restored at 1505 on August 12, 1982.

DESIGNATION OF APPARENT CAUSE:

The cause of this event is attributed to dirty terminals.

ANAYLSIS OF OCCURRENCE:

Reactor Coolant Temperature indication was available in the other loop. There was no effect upon the health or safety of the general public.

CORRECTIVE ACTION:

The instrument lugs and terminals were cleaned and determined operable. No further corrective action is considered necessary.

FAILURE DATA:

This was the third occurrence for this instrument and the eleventh event reported under this specification.