NRC FORM 366
(7-77)

LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0 1] [C T M N S 2] (2) [0 0 - 0 0 0 0 - 0 0 0] (3) [4 1 1 1 1] (4) [ ] (5)
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
[0 1] REPORT SOURCE [L] (6) [0 5 0 0 0 3 3 6] (7) [0 8 1 9 8 1] (8) [0 9 1 6 8 1] (9)
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[0 2] During routine surveillance testing and with the plant at 100 per cent power,
[0 3] the Turbine Driven Auxiliary Feedwater Pump was taken out of service to repair
[0 4] the manual operator on the Throttle Control Valve SV 4188. The Motor Driven
[0 5] Auxiliary Feedwater Pumps were verified operable and the plant was operated in
[0 6] accordance with Technical Specification Action Statement 3.7.1.2B. The operator
[0 7] was repaired and the Auxiliary Feedwater Pump returned to service within 2 hours.
[0 8] Similar LER's - None.
7 8 9 80

[0 9] SYSTEM CODE [W E] (11) CAUSE CODE [E] (12) CAUSE SUBCODE [B] (13) COMPONENT CODE [V A L V E X] (14) COMP. SUBCODE [F] (15) VALVE SUBCODE [G] (16)
7 8 9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER: EVENT YEAR [8 1] 21 22 [—] 23 SEQUENTIAL REPORT NO. [0 3 0] 24 26 [/] 27 OCCURRENCE CODE [0 3] 28 29 REPORT TYPE [L] 30 [—] 31 REVISION NO. [0] 32

ACTION TAKEN [B] (18) 33 FUTURE ACTION [Z] (19) 34 EFFECT ON PLANT [Z] (20) 35 SHUTDOWN METHOD [Z] (21) 36 HOURS (22) [0 0 0 0] 37 40 ATTACHMENT SUBMITTED [N] (23) 41 NPRD-4 FORM SUB. [Y] (24) 42 PRIME COMP. SUPPLIER [A] (25) 43 COMPONENT MANUFACTURER [L 2 0 0] (26) 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

[1 0] The Handwheel Retaining Ring on the Throttle Control Valve was found broken, im-
[1 1] pairing manual (Local) control on the Throttle Control Valve. The pump was taken
[1 2] out of service, a new Retaining Ring installed and the Auxiliary Feedwater Pump
[1 3] returned to service with full local and remote control. (Limitorque Type SMB-000-,
[1 4] 1-403-0034-4, Part 73)
7 8 9 80

[1 5] FACILITY STATUS [E] (28) 9 % POWER [1 0 0] (29) 10 12 OTHER STATUS (30) [NA] 13 44 METHOD OF DISCOVERY [B] (31) 45 46 DISCOVERY DESCRIPTION (32) [Preventive Maintenance] 80
7 8

[1 6] ACTIVITY RELEASED [Z] (33) 9 CONTENT OF RELEASE [Z] (34) 10 AMOUNT OF ACTIVITY (35) [NA] 11 44 45 LOCATION OF RELEASE (36) [NA] 80
7 8

[1 7] PERSONNEL EXPOSURES NUMBER [0 0 0] (37) 9 11 TYPE [Z] (38) 12 DESCRIPTION (39) [NA] 13 80
7 8

[1 8] PERSONNEL INJURIES NUMBER [0 0 0] (40) 9 11 DESCRIPTION (41) [NA] 12 80
7 8

[1 9] LOSS OF OR DAMAGE TO FACILITY TYPE [Z] (42) 9 DESCRIPTION (43) [NA] 10 80
7 8

[2 0] PUBLICITY ISSUED [N] (44) 7 DESCRIPTION (45) [NA] 58 NRC USE ONLY [ ] 69 80
7 8

8109280518 810916
PDR ADOCK 05000336
S PDR

John Criscione (203) 447-1791