LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | | (1–6)

Big Rock Point
(PLEASE PRINT ALL REQUIRED INFORMATION)

	LICENSEE NAME	LICENSE NUMBER	LICENSE TYPE	EVENT TYPE
01	MIBRP1	00-00000-00	41111	01

	CON'T	REPORT TYPE	REPORT SOURCE	DOCKET NUMBER	EVENT DATE	REPORT DATE
01		L	L	050-0155	050377	051677

EVENT DESCRIPTION

02 Following component failure which rendered one of four Reactor Depressurization
03 System actuation channels inoperable, testing of the remaining three channels was
04 not done in four hours as required by the Technical Specification 4.1.5E. The de-
05 fective channel was repaired and satisfactorily tested within six hours. The com-
06 ponent failure* and the specific administrative failure are not repetitive.

(RO-77-15)

	SYSTEM CODE	CAUSE CODE	COMPONENT CODE	PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER	VIOLATION
07	SH	A	ZZZZZZ	Z	Z999	Y

CAUSE DESCRIPTION

08 Assessment of the time involved to return the inoperable channel to service and com-
09 plete the test was in error. The incident has been reviewed with personnel involved
10 emphasizing the necessity to implement required surveillance testing as soon (Contd).

	FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
11	E	035	NA	A	Review of Operations Records

	FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
12	Z	Z	NA	NA

PERSONNEL EXPOSURES

	NUMBER	TYPE	DESCRIPTION
13	000	Z	NA

PERSONNEL INJURIES

	NUMBER	DESCRIPTION
14	000	NA

PROBABLE CONSEQUENCES

15 None - Only three channels are needed to fulfill the design function.

LOSS OR DAMAGE TO FACILITY

	TYPE	DESCRIPTION
16	Z	NA

PUBLICITY

17 None

ADDITIONAL FACTORS

18 (Cause Description - Contd) - as possible. *See RO-77-17.

19 NA

8110060658 770516
PDR ADOCK 05000155
S PDR