Unit 2

# LICENSEE EVENT REPORT

CONTROL BLOCK: [ | | | | | ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | T N S N P 2 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE (9–14) | LICENSE NUMBER (15–25) | LICENSE TYPE (26–30) | CAT (57–58)

CON'T
0 1 | REPORT SOURCE L (6) | 0 5 0 0 0 3 2 8 (7) | 0 3 2 7 8 2 (8) | 0 4 2 3 8 2 (9)
DOCKET NUMBER (61–68) | EVENT DATE (69–74) | REPORT DATE (75–80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 With unit 2 in mode 1 (100% power, 578 degrees F, 2235 psig) at 0925 CST on 03/27/82,
0 3 one automatic control valve (2-LCV-3-171) in the auxiliary feedwater system was
0 4 declared inoperable due to failure to open on command. This event placed the unit
0 5 in action statement (a) of LCO 3.7.1.2. There was no effect upon public health and
0 6 safety. Previous occurrences: two (SQRO-50-327/82036 and 328/82038).
0 7
0 8

| 0 9 | SYSTEM CODE | CAUSE CODE | CAUSE SUBCODE | COMPONENT CODE | COMP. SUBCODE | VALVE SUBCODE |
|---|---|---|---|---|---|---|
| | W B (11) | E (12) | E (13) | I N S T R U (14) | X (15) | Z (16) |

| (17) LER/RO REPORT NUMBER | EVENT YEAR | | SEQUENTIAL REPORT NO. | | OCCURRENCE CODE | REPORT TYPE | | REVISION NO. |
|---|---|---|---|---|---|---|---|---|
| | 8 2 | — | 0 4 2 | / | 0 3 | L | — | 0 |

| ACTION TAKEN | FUTURE ACTION | EFFECT ON PLANT | SHUTDOWN METHOD | HOURS (22) | ATTACHMENT SUBMITTED | NPRD-4 FORM SUB. | PRIME COMP. SUPPLIER | COMPONENT MANUFACTURER |
|---|---|---|---|---|---|---|---|---|
| A (18) | Z (19) | Z (20) | Z (21) | 0 0 0 0 | N (23) | N (24) | L (25) | M 1 2 0 |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Investigation revealed that the pneumatic relay for the Masc··ilan Model 8012
1 1 electro-pneumatic positioner failed to function properly. The cause for the relay
1 2 malfuncti· is unknown. The pneumatic relay was replaced and the valve
1 3 returned to service on 03/28/82.
1 4

| 1 5 | FACILITY STATUS | % POWER | OTHER STATUS (30) | METHOD OF DISCOVERY | DISCOVERY DESCRIPTION (32) |
|---|---|---|---|---|---|
| | E (28) | 1 0 0 (29) | NA | B (31) | Operator observation |

| 1 6 | ACTIVITY RELEASED | CONTENT OF RELEASE | AMOUNT OF ACTIVITY (35) | LOCATION OF RELEASE (36) |
|---|---|---|---|---|
| | Z (33) | Z (34) | NA | NA |

PERSONNEL EXPOSURES

| 1 7 | NUMBER | TYPE | DESCRIPTION (39) |
|---|---|---|---|
| | 0 0 0 (37) | Z (38) | NA |

PERSONNEL INJURIES

| 1 8 | NUMBER | DESCRIPTION (41) |
|---|---|---|
| | 0 0 0 (40) | NA |

LOSS OF OR DAMAGE TO FACILITY (43)

| 1 9 | TYPE | DESCRIPTION |
|---|---|---|
| | Z (42) | NA |

PUBLICITY

| 2 0 | ISSUED | DESCRIPTION (45) | NRC USE ONLY |
|---|---|---|---|
| | N (44) | NA | |

8206010439

Name of Preparer: H. R. Rogers /M. R. Harding Phone: (615) 751-0349