NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | N J S G S 2 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
01 | REPORT SOURCE L (6) | 0 5 0 0 0 3 1 1 (7) | 0 3 0 7 8 2 (8) | 0 3 3 1 8 2 (9)
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | On March 7, 1982 an undervoltage condition in No. 2A Safeguards Equipment Control
03 | (SEC) Cabinet caused a Mode 1 No. 2A SEC actuation. No. 2A Diesel Generator started
04 | and all safety-related loads were energized. The SEC actuation could not be reset
05 | and No. 2A SEC cabinet was de-energized. At 0830 hours Limiting Condition for
06 | Operation 3.3.2.b Action 13 was entered.
07 |
08 |
7 8 9 80

09 | SYSTEM CODE I B (11) | CAUSE CODE E (12) | CAUSE SUBCODE G (13) | COMPONENT CODE I N S T R U (14) | COMP. SUBCODE X (15) | VALVE SUBCODE Z (16)
7 8 9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER | EVENT YEAR 8 2 | — | SEQUENTIAL REPORT NO. 0 1 9 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0
21 22 23 24 26 27 28 29 30 31 32

ACTION TAKEN C (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED Y (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER V 1 3 2 (26)
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The cause of the SEC actuation was failure of the Card File Assembly in No. 2A SEC
11 | Cabinet. No. 2A Diesel Generator and all electrical loads that started as a result of
12 | the SEC actuation were secured. A new Card File Assembly was installed in No. 2A
13 | SEC Cabinet and Surveillance Procedure M3B was satisfactorily performed. No. 2A SEC
14 | was declared operable, and at 1146 hours, March 7, 1982 Limiting Condition for Oper-
7 8 9 ation 3.3.2.b Action 13 was terminated. 80

15 | FACILITY STATUS E (28) | % POWER 0 9 9 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Operator Observation
7 8 9 10 12 13 44 45 46 80

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA
7 8 9 10 11 44 45 80

17 | PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA
7 8 9 11 12 13 80

18 | PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) NA
7 8 9 11 12 80

19 | LOSS OF OR DAMAGE TO FACILITY (43) TYPE Z (42) | DESCRIPTION NA
7 8 9 10 80

20 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA | NRC USE ONLY
7 8 9 10 68 69 80

8204160233 820331
PDR ADOCK 05000311
S PDR

NAME OF PREPARER R. Frahm PHONE: 609-935-0998

GPO 917-926