LICENSEE EVENT REPORT

CONTROL BLOCK: |__|__|__|__|__|__| (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| 0 | 1 | | N | Y | I | P | S | 3 | (2) | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | (3) | 4 | 1 | 1 | 1 | 1 | 1 | (4) | | | (5) |

LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE 30 — 57 CAT 58

CON'T

| 0 | 1 | | REPORT SOURCE | L | (6) | 0 | 5 | 0 | 0 | 0 | 2 | 8 | 6 | (7) | 0 | 3 | 2 | 7 | 8 | 2 | (8) | 0 | 4 | 0 | 9 | 8 | 2 | (9) |

DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

| 0 | 2 | While at cold shutdown during a refueling outage, a small leak on the

| 0 | 3 | shell side of steam generator no. 32 was observed. An oval-shaped hole

| 0 | 4 | was discovered in the upper girth weld of the generator. The hole

| 0 | 5 | measures approximately 5/8 inch by 1/8 inch. As the steam generator

| 0 | 6 | shell is considered to be an extension of the primary containment

| 0 | 7 | boundary, this event is reportable under Technical Specification

| 0 | 8 | 6.9.1.7.C.

| 0 | 9 | SYSTEM CODE [C | B] (11) CAUSE CODE [E] (12) CAUSE SUBCODE [B] (13) COMPONENT CODE [H | T | E | X | C | H] (14) COMP. SUBCODE [F] (15) VALVE SUBCODE [Z] (16)

(17) LER RO REPORT NUMBER EVENT YEAR [8 | 2] [—] SEQUENTIAL REPORT NO. [0 | 0 | 2] [/] OCCURRENCE CODE [0 | 1] REPORT TYPE [T] [—] REVISION NO. [0]

| ACTION TAKEN [X] (18) | FUTURE ACTION [X] (19) | EFFECT ON PLANT [Z] (20) | SHUTDOWN METHOD [Z] (21) | HOURS (22) [0 | 0 | 0 | 0] | ATTACHMENT SUBMITTED [N] (23) | NPRD-4 FORM SUB. [Y] (24) | PRIME COMP. SUPPLIER [N] (25) | COMPONENT MANUFACTURER [W | 1 | 2 | 0] (26) |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

| 1 | 0 | As the leak was on the secondary side of the generator, secondary water

| 1 | 1 | level was lowered to a point below that of the hole, thereby terminating

| 1 | 2 | the leakage. Further analysis of this event and repair of the steam

| 1 | 3 | generator shell will be performed during the present refueling outage. No

| 1 | 4 | similar events have been reported to date.

| 1 | 5 | FACILITY STATUS [H] (28) | % POWER [0 | 0 | 0] (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY [B] (31) | DISCOVERY DESCRIPTION (32) VC Inspection |

| 1 | 6 | ACTIVITY RELEASED [Z] (33) | CONTENT OF RELEASE [Z] (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA |

| 1 | 7 | PERSONNEL EXPOSURES NUMBER [0 | 0 | 0] (37) | TYPE [Z] (38) | DESCRIPTION (39) NA |

| 1 | 8 | PERSONNEL INJURIES NUMBER [0 | 0 | 0] (40) | DESCRIPTION (41) NA |

| 1 | 9 | LOSS OF OR DAMAGE TO FACILITY TYPE [Z] (42) | DESCRIPTION (43) NA |

| 2 | 0 | PUBLICITY ISSUED [Y] (44) | DESCRIPTION (45) Press release issued by PASNY. | NRC USE ONLY [|__|__|__|__|__|__|__|__|__|__|] |

J. Gumble   PHONE: 914-739-8200,X217