# LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | N C B E P 2 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 | REPORT SOURCE L (6) | 0 5 0 - 0 3 2 4 (7) | 1 1 0 1 7 8 (8) | 1 1 3 0 7 8 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During the rod block monitor (RBM) periodic test (PT 1.5.1), RBM channel A was
03 found out of calibration.
04 (Technical Specification 3.1.4.3)
05
06
07
08

09 SYSTEM CODE R B (11) | CAUSE CODE x (12) | CAUSE SUBCODE Z (13) | COMPONENT CODE I N S T R U (14) | COMP. SUBCODE X (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 7 8 | — | SEQUENTIAL REPORT NO. 0 7 2 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN E (18) | FUTURE ACTION X (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER G 0 8 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The RBM was out of calibration due to setpoint drift. The monitor was
11 recalibrated and returned to service. Frequency of calibration for the monitor
12 will be increased from once per year, to twice per year. This action should
13 prevent similar events from occurring.
14

15 FACILITY STATUS E (28) | % POWER 0 9 9 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Periodic Test

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

17 PERSONNEL EXPOSURES: NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA

18 PERSONNEL INJURIES: NUMBER 0 0 0 (40) | DESCRIPTION (41) NA

19 LOSS OF OR DAMAGE TO FACILITY: TYPE Z (42) | DESCRIPTION NA (43)

20 PUBLICITY: ISSUED N (44) | DESCRIPTION (45) NA | NRC USE ONLY

7812070181

NAME OF PREPARER A. C. Tollison, Jr. PHONE: 919 - 457-6701

GPO 917-926