NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

# LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | C O F S V 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 2 0 (4) | (5)
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
01 | REPORT SOURCE L (6) | 0 5 0 0 0 2 6 7 (7) | 0 7 1 2 8 2 (8) | 0 8 1 1 8 2 (9)
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | On three occasions during the month of July, the emergency feedwater headers to the
03 | helium circulator pelton wheel drives were isolated to perform maintenance on leaking
04 | header safety valves. With the reactor operating at approximately 70% power during
05 | each of these occasions, this constitutes a degraded mode of LCO 4.2.2(a) and is re-
06 | portable per Fort St. Vrain Technical Specification AC 7.5.2(b)2. Similar occurrence
07 | is RO 81-046. No affect on public health or safety.
08 |
7 8 9 80

09 | SYSTEM CODE H H (11) | CAUSE CODE E (12) | CAUSE SUBCODE B (13) | COMPONENT CODE V A L V E X (14) | COMP. SUBCODE X (15) | VALVE SUBCODE B (16)
7 8 9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER: EVENT YEAR 8 2 (21 22) | — (23) | SEQUENTIAL REPORT NO. 0 2 9 (24 26) | / (27) | OCCURRENCE CODE 0 3 (28 29) | REPORT TYPE L (30) | — (31) | REVISION NO. 0 (32)

ACTION TAKEN B (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 (37 40) | ATTACHMENT SUBMITTED Y (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER D 2 4 3 (26)
33 34 35 36 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | Repair of four Dresser 1500# Consolidated Safety Relief Valves, Model No. 1916-Gc/Pl,
11 | required rework of the seats and discs to eliminate internal leakage through the
12 | valves, and thus, necessitated the isolation of the helium circulator pelton wheel
13 | drives. The valves were repaired, and pelton wheel drives returned to service within
14 | time allowed by LCO 4.2.2. No further corrective action anticipated or required.
7 8 9 80

15 | FACILITY STATUS E (28) | % POWER 0 7 0 (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Operator Observation
7 8 9 10 12 13 44 45 46 80

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A
7 8 9 10 11 44 45 80

17 | PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) N/A
7 8 9 11 12 13 80

18 | PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) N/A
7 8 9 11 12 80

8208200141 820811
PDR ADOCK 05000267
S PDR

19 | LOSS OF OR DAMAGE TO FACILITY (43) TYPE Z (42) | DESCRIPTION N/A
7 8 9 10 80

20 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) N/A | NRC USE ONLY
7 8 9 10 68 69 80

NAME OF PREPARER Charles Fulk PHONE: (303) 785-2224

GPO 917-926