NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

UPDATE REPORT - Previous
Report Date 9/12/79

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

Line	Field	Value
01	LICENSEE CODE (2)	G A E I H 1
01	LICENSE NUMBER (3)	0 0 - 0 0 0 0 0 - 0 0
01	LICENSE TYPE (4)	4 1 1 1 1
01	CAT (5)	
CON'T 01	REPORT SOURCE (6)	L
01	DOCKET NUMBER (7)	0 5 0 0 0 3 2 1
01	EVENT DATE (8)	0 8 2 5 7 9
01	REPORT DATE (9)	1 1 0 2 8 2

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On August 25, 1979, with Unit 1 at hot standby, an attempt to perform the
03 "RCIC PUMP OPERABILITY" procedure was unsuccessful when the turbine
04 failed to trip upon manual signal. On August 27, 1982, the turbine trip
05 and throttle valve again failed to respond to a trip signal. The RCIC
06 system was declared inoperable. This event is contrary to T.S.3.5.E.1. A
07 7-day LCO was initiated as per Tech. Specs. 3.5.3.E.2. The health and
08 safety of the public were not affected by this non-repetitive event.

Line	Field	Value
09	SYSTEM CODE (11)	C E
09	CAUSE CODE (12)	E
09	CAUSE SUBCODE (13)	B
09	COMPONENT CODE (14)	V A L V E X
09	COMP. SUBCODE (15)	E
09	VALVE SUBCODE (16)	D
(17) LER/RO REPORT NUMBER	EVENT YEAR	7 9
		—
	SEQUENTIAL REPORT NO.	0 8 2
		/
	OCCURRENCE CODE	0 3
	REPORT TYPE	X
		—
	REVISION NO.	1
	ACTION TAKEN (18)	A
	FUTURE ACTION (19)	B
	EFFECT ON PLANT (20)	Z
	SHUTDOWN METHOD (21)	Z
	HOURS (22)	0 0 0 0
	ATTACHMENT SUBMITTED (23)	N
	NPRD-4 FORM SUB. (24)	N
	PRIME COMP. SUPPLIER (25)	A
	COMPONENT MANUFACTURER (26)	T 1 4 7

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The August 25, 1982, failure was due to burned out turbine trip actuator
11 coils. The burned out coils were replaced. The system was satisfactorily
12 tested and returned to service. The August 27, 1982 failure was caused
13 by binding in the spring cylinder assembly. The spring cyclinder assembly
14 was replaced and the valve tested satisfactorily and returned to service.

Line	Field	Value
15	FACILITY STATUS (28)	G
15	% POWER (29)	0 0 0
15	OTHER STATUS (30)	NA
15	METHOD OF DISCOVERY (31)	B
15	DISCOVERY DESCRIPTION (32)	Surveillance Test
16	ACTIVITY RELEASED (33)	Z
16	CONTENT OF RELEASE (34)	Z
16	AMOUNT OF ACTIVITY (35)	NA
16	LOCATION OF RELEASE (36)	NA
17	PERSONNEL EXPOSURES NUMBER (37)	0 0 0
17	TYPE (38)	Z
17	DESCRIPTION (39)	NA
18	PERSONNEL INJURIES NUMBER (40)	0 0 0
18	DESCRIPTION (41)	NA
19	LOSS OF OR DAMAGE TO FACILITY TYPE (42)	Z
19	DESCRIPTION (43)	NA
20	PUBLICITY ISSUED (44)	N
20	DESCRIPTION (45)	NA
20	NRC USE ONLY	

8211150300 821102
PDR ADOCK 05000321
S PDR

NAME OF PREPARER S. B. Tipps PHONE: (912) 367-7851

GPO 917-926