(9-77)

Unit 2

# LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | TNSNP2 (2) | 00-00000-00 (3) | 4111 1 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 | REPORT SOURCE L (6) | 05000328 (7) | 102182 (8) | 111782 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 With unit 2 in mode 1 (80% power) at 0514 CST on 10/21/82, one pressurizer
03 pressure channel was declared inoperable due to loss of power to the channel.
04 This event required entry into action statement 6 of LCO 3.3.1. There was no
05 effect upon public health and safety. Previous occurrences - none.
06
07
08

09 | SYSTEM CODE IA (11) | CAUSE CODE E (12) | CAUSE SUBCODE A (13) | COMPONENT CODE INSTRU (14) | COMP. SUBCODE P (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 82 — SEQUENTIAL REPORT NO. 122 — OCCURRENCE CODE 03 — REPORT TYPE L — REVISION NO. 0

ACTION TAKEN A (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS 0000 (22) | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER L (25) | COMPONENT MANUFACTURER F180

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Pressurizer pressure channel 2-PS-68-323B was found to have lost its AC power
11 supply due to a loose fuse. This was caused by a defective fuse holder cap
12 allowing an interruption of power to the channel. The fuse holder cap was
13 replaced and the channel returned to service at 0930 CST on 10/21/82. This
14 failure is an isolated case and warrants no further action.

15 | FACILITY STATUS E (28) | % POWER 080 (29) | OTHER STATUS NA (30) | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION Operator observation (32)

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY NA (35) | LOCATION OF RELEASE NA (36)

17 | PERSONNEL EXPOSURES NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION NA (39)

18 | PERSONNEL INJURIES NUMBER 000 (40) | DESCRIPTION NA (41)

19 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION NA

8211230091 821117
PDR ADOCK 05000328
S PDR

20 | PUBLICITY ISSUED N (44) | DESCRIPTION NA (45)

NRC USE ONLY

Name of Preparer: H. R. Rogers /M. R. Harding Phone: (615) 751-0349