DOCKET NO. 50-295
UNIT NAME Zion Unit 1
DATE 01/28/91
COMPLETED BY R. Herron
TELEPHONE (708) 746-2084

REPORT MONTH DECEMBER 1990

No.	Date	Type[1]	Duration (Hours)	Reason[2]	Method of Shutting Down Reactor[3]	Licensee Event Report #	System Code[4]	Component Code[5]	Cause & Corrective Action to Prevent Recurrence
5	901204	F	*652.8	A	1				Outage forced by bypass valve packing leak.

[1]
F: Forced
S: Scheduled

[2]
Reason:
A-Equipment Failure (Explain)
B-Maintenance of Test
C-Refueling
D-Regulatory Restriction
E-Operator Training & Licensee Examination
F-Administrative
G-Operational Error (Explain)
H-Other (Explain)

[3]
Method
1-Manual
2-Manual Scram
3-Auto Scram
4-Continued
5-Reduced Load

[4]
Exhibit G - Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File (NUREG-0161)

[5]
Exhibit 1 - Same Source

* Correction made to NO.6; 652.5 hours incorrectly reported. Correct hours are 652.8 resulting in an increase of .3 to forced outage hours for 12/04/90.