LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | TNSNP1 (2) | 00-00000-00 (3) | 41111 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T 01 | REPORT SOURCE L (6) | 05000327 (7) | 091482 (8) | 101382 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

During the performance of SI-220, "Load Sequence Timer Functional Test," on fire pump 1B-B start circuit, it was discovered that the time delay setpoint on relay 1B2 was found to be 132.5 seconds which is out of the 5% tolerance of 120 seconds. This is in violation of surveillance requirement 4.8.1.1.2.D.12.

09 | SYSTEM CODE AB (11) | CAUSE CODE E (12) | CAUSE SUBCODE A (13) | COMPONENT CODE RELAYX (14) | COMP. SUBCODE J (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 82 — SEQUENTIAL REPORT NO. 117 — OCCURRENCE CODE 03 — REPORT TYPE L — REVISION NO. 0

ACTION TAKEN F (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS 0000 (22) | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER W12

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

The time delay setpoint was readjusted to 120.5 seconds which is within the 5% tolerance.

15 | FACILITY STATUS G (28) | % POWER 000 (29) | OTHER STATUS NA (30) | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Surveillance testing

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY NA (35) | LOCATION OF RELEASE NA (36)

17 | PERSONNEL EXPOSURES NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION NA (39)

18 | PERSONNEL INJURIES NUMBER 000 (40) | DESCRIPTION NA (41)

8210190386 821014
PDR ADOCK 05000327
S PDR

19 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION NA (43)

20 | PUBLICITY ISSUED N (44) | DESCRIPTION NA (45)

NRC USE ONLY

Name of Preparer: W. D. Romine /M. R. Harding Phone: (615) 751-0349