(7-77)

LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1	M N P I N 2 (2)	0 0 - 0 0 0 0 0 - 0 0 (3)	4 1 1 1 1 (4)	(5)		
	LICENSEE CODE	LICENSE NUMBER	LICENSE TYPE	CAT		

CON'T 0 1	REPORT SOURCE: L (6)	DOCKET NUMBER: 0 5 0 0 0 3 0 6 (7)	EVENT DATE: 0 3 0 3 8 3 (8)	REPORT DATE: 0 3 2 4 8 3 (9)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During surveillance testing, excessive leakage from the maintenance airlock was
0 3 measured. The primary leakage path was the outboard upper shaft seal. Leakage was
0 4 about 25,000 sccm. The total leakage for type B & C tests were not exceeded. Last
0 5 similar event was RO-80-15. Tech Spec 4.4.A.4.c. applies. No effect on public
0 6 health and safety.
0 7
0 8

	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
0 9	S A (11)	E (12)	B (13)	X X X X X X (14)	Z (15)	Z (16)

(17) LER/RO REPORT NUMBER	EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
	8 3	—	0 0 4	/	0 3	L	—	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
E (18)	Z (19)	Z (20)	Z (21)	0 0 0 0	N (23)	Y (24)	L (25)	X 9 9 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Deterioration of Grafoil packing at the shaft seal. Packing was tightened.
1 1
1 2
1 3
1 4

	FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
1 5	G (28)	0 0 0 (29)	NA	B (31)	Surveillance test

	ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
1 6	Z (33)	Z (34)	NA	NA

PERSONNEL EXPOSURES

	NUMBER	TYPE	DESCRIPTION (39)
1 7	0 0 0 (37)	Z (38)	NA

PERSONNEL INJURIES

	NUMBER	DESCRIPTION (41)
1 8	0 0 0 (40)	NA

LOSS OF OR DAMAGE TO FACILITY (43)

	TYPE	DESCRIPTION
1 9	Z (42)	NA

8304040423 830324
PDR ADOCK 05000306
S PDR

PUBLICITY

	ISSUED	DESCRIPTION (45)	NRC USE ONLY
2 0	N (44)	NA	

NAME OF PREPARER A. A. Hunstad PHONE: 612-388-1121

GPO 917-926