(7-77)

# LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | G A E 1 H 2 (2) | 0 0 0 0 0 0 0 0 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 | REPORT SOURCE L (6) | 0 5 0 0 0 3 6 6 (7) | 0 9 2 1 7 8 (8) | 1 0 0 4 7 8 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During start-up testing, while performing procedure HNP-2-5234 on the main steam
03 line tunnel temperature switches, the setpoint of 2B21-N013C was found to be higher
04 than 200 F. (T. S. 3.3.2 Table 3.3.2-2 and T. S. 3.3.2 Table 3.3.2-1)
05
06
07
08

09 | SYSTEM CODE C D (11) | CAUSE CODE E (12) | CAUSE SUBCODE E (13) | COMPONENT CODE I N S T R U (14) | COMP. SUBCODE S (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER | EVENT YEAR 7 8 | — | SEQUENTIAL REPORT NO. 0 4 1 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN E (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER F 0 8 1 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The setpoint of temperature switch 2B21-N013C, a fenwal switch, had drifted from
11 200 F. to 214 F. The switch was recalibrated per HNP-2-5234.
12
13
14

15 | FACILITY STATUS B (28) | % POWER 0 0 0 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY Z (31) | DISCOVERY DESCRIPTION (32) NA

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

17 | PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA

18 | PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) NA

19 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) NA

20 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA | NRC USE ONLY

7810170314

NAME OF PREPARER R. T. Nix
Superintendent of Maintenance

PHONE: (912) 367-7781

GPO 917-926