DEPARTMENT OF THE NAVY
NAVAL SEA SYSTEMS COMMAND DETACHMENT
RADIOLOGICAL AFFAIRS SUPPORT OFFICE (RASO)
NWS P.O. DRAWER 260
YORKTOWN, VA 23691-0260

ENTER INTO DATABASE
FILE: LICENSE:
PERMIT: ✓
YEARLY:
COPY TO PDR
OTHER

5104/65236
Ser 02B/991394/0655
20 September 1999

From: Officer in Charge, Naval Sea Systems Command Detachment, Radiological Affairs Support Office (RASO)
To: Commanding Officer, Space and Naval Warfare Systems Center, Charleston

Subj: RADIOLOGICAL AFFAIRS SUPPORT PROGRAM (RASP) INSPECTION OF SPACE AND NAVAL WARFARE SYSTEMS CENTER, CHARLESTON, 16-17 SEPTEMBER 1998

Ref: (a) NRSC ltr 5104 Ser N455C/8U589046 of 2 Oct 98
(b) SPAWARSYSCEN Charleston ltr 9492 Ser 322DH/139 of 9 Sep 99
(c) SPAWARSYSCEN Charleston ltr 9492 Ser 322DH/115 of 5 Aug 99
(d) SPAWARSYSCEN Charleston ltr 9492 Ser 322DH/097 of 13 Jul 99

1. Reference (a) reported deficiencies as the result of the subject inspection of RADIAC calibration operations authorized by Naval Radioactive Materials Permit (NRMP) No. 39-65236-C2NP. Your responses to these deficiencies, references (b), (c) and (d), have been reviewed and are considered satisfactory.

2. Corrective actions will be verified during the next inspection. This letter serves as the final closing action for administrative purposes.

3. NAVSEADET RASO point of contact is Mr. Timothy P. Hart, NAVSEADET RASO, DSN 953-4692 or commercial (757) 887-4692.

S. W. Doremus
S. W. DOREMUS

Copy to:
CNO (N45)
NRC Region II
COMNAVSEASYSCOM (SEA 04LR)

mc21